Form 9-3ar (May 1963)

UNITED STATES

SUBMIT IN TRIPLICATE*
(Other instructions on re-

Form approved. Budget Bureau No. 42-R1424.

DEPARIMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO. NM-2244
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	
1.	7. UNIT AGREEMENT NAME
WELL X GAS OTHER	S, FARM OR LEASE NAME
2. NAME OF OPERATOR Samedan Oil Componation	Hughes Federal
Samedan Oil Corporation 3. ADDRESS OF OPERATOR	9. WELL NO.
10 Desta Drive - Suite 240 East, Midland, Texas 79705 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	4
See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
At surface	Langlie-Mattix 11. SEC., T., B., M., OR BLK. AND
Unit Letter I, 2180' FSL & 660' FEL	SURVEY OR AREA
	Sec. 17, T-23-S, R-37-E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
3333' GR	Lea New Mexico
16. Check Appropriate Box To Indicate Nature of Notice, Report, o	r Other Data
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT SHOOTING OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT* X
SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS (Other)	ABANDONAENT
(Note: Report res	ults of multiple completion on Well ompletion Report and Log form.)
3-22-88 Set 5½" CIBP @ 3400' and cap with 3 sacks cemer Spot 50 sacks plug @ 2500'. Spot 50 sacks plug @ 1400'. Spot 20 sacks plug @ 600'. Spot 10 sacks surface plug. Weld on steel plate and ins dry hole marker.	APR 5 10 W
	ED 1880
18. I hereby certify that the foregoing is true and correct SIGNED	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1