

Form 3160-5
(June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N.M. Oil Cons. Division
Box 1980
Hobbs, NM 88241

SUNDAY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0133
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM84897

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

CONOCO FED. 26 #1

9. API Well No.

30-025-25685

10. Field and Pool, or Exploratory Area

EAST EL MAR, DELAWARE

11. County or Parish, State

LEA COUNTY, NM

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

RALPH E. WILLIAMSON

3. Address and Telephone No.

P.O. BOX 994 MIDLAND, TX 79702

(915) 683-2200

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' Fs & EL's of Section 26, Twp. 26-S, R 33-E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Report

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 12-7-95 Dug and fenced working pit.
12-12-95 Clean prod. tanks and empty treater.
1-02-96 Rigged up and SD.
1-03-96 Ran 130 bbls. FW and 260 bbls. BW in tanks. COH w/rods and tbgs. Lay down rods.
1-04-96 Ran CIBP in hole and set @ 5171'. RIH w/tbg. SD
Circulate hole w/mud. Pump 35' cement plug. COH w/42 jts tbgs and layed down.
Remove 4 1/2" WH. Screw on pull nipple, pull free point. Shot Csg @ 2024', pull csg.
1-05-96 Pumped 25 sacks cement plug. COH w/tbg. SD.
RIH tag plug @ 1840', COH, weld pull nipple on and free point 7" csg. Shot csg
1-08-96 @ 1020', plug csg. SD.
RIH, pump 25 sacks cement on plug. SD 4 hours. RIH, tag plug @ 944'. CUH to 685'
1-09-96 pump 25 sacks on plug. COH SD.
RIH, tag plug @ 433'. COH, set surface plug. Rig down.
1-15-96 Weld on dry hole marker and cut anchors. Move equip from location.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct.

Signed David R. Glass
(This space for Federal or State official use)
(ORIG. SGD.) DAVID R. GLASS

Title AGENT

Date 2-1-96

Approved by
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date FEB 09 1999

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side