

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL ☐ GAS WELL ☐ OTHER ☒ convert to WIW

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

7990 IH 10 West, San Antonio, TX 78230

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1920 FSL ⁵¹⁰ & ~~660~~ FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether D.P., R.Y., CR., etc.)

3014 KB 3003 CL

6. LEASE DESIGNATION AND SERIAL NO.

NM-7951

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Leonard Bros.

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

S. Leonard

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 13, T26S, R37E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PLUG OR ALTER CASING

☐
☐
☐
☐

WATER SHUT-OFF

☐
☐
☒
☐

REPAIRING WELL

☐
☐
☐
☐

FRAC-TURE TREAT

WELL-FILE COMPLETE

FRAC-TURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANE

(Other) convert to WIW

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU PU.
2. Pull rods and pump.
3. NUBOP. Tag bottom and pull tubing.
4. RIH w/2 7/8" tubing and treating PKR. Set PKR at 3300'. Treat perms w/xylene/15% HCL. Flush tbq. w/2% KCL.
5. Unset PKR. POOH w/PKR and Tbg.
6. RIH w/plastic coated tbq. and plastic coated Guiberson uni-packer I. Circulate hole w/2% KCL containing corrosion inhibitor, oxygen scavenger and biocide.
7. Set pkr at 3200'. NUBOP.
8. Hook up injection line.
9. RDPU.

18. I hereby certify that the foregoing is true and correct.

SIGNED

Robert A. Mathew

TITLE Production Eng. Supv.

DATE 8-2-84

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY

AWQ

TITLE

Subject to
Like Approval
by State

DATE

CONDITIONS OF APPROVAL IF 8/1984

Carlsbad

NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

AUG 13 1984

O.C.D.
HOBBS OFFICE