

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

O+6 - NMOCD - P.O. Box 1980 1 - Foreman-HC
Hobbs, NM 88240 1 - Engr.-RH
1 - MidlandAdmin. Unit - Mr. J.A.
1 - Laura Richardson-Midland 1 - File

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1327

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator	Myers Langlie Mattix
3. Address of Operator	8. Farm or Lease Name
4. Location of Well	9. Well No.
UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM	10. Field and Pool, or Wildcat
THE East LINE, SECTION 32 TOWNSHIP 23S RANGE 37E NMPM.	Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3294' = GL	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING
PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up PU and pull rods, pmp and 2 7/8" tbq.
2. TIH with workstring RBP and pkr. and squeeze perfs 3429'-3494'.
3. WOC 24 hrs. Release pkr. and TOH.
4. TIH with workstring and bit and clean out to RBP. TOH w/bit.
5. TIH w/workstring, seating nipple, and retrieving tool. Swab test squeeze job.
6. Recover RBP. TIH w/bit and clean out well to TD. TOH w/tools.
7. Perforate 5 1/2" csg. from 3601'-3701' using 4" csg. gun.
8. TIH with workstring and pkr. and fracture treat perfs 3545'-3701'.
9. TOH with workstring and pkr.
10. TIH with production tbq., rods and pump and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Bill R. Crockett TITLE Area Superintendent DATE 12/22/83

APPROVED BY JERRY SEXTON
CONDITIONS OF APPROVAL, IF ANY:

DEC 30 1983