

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.
17191

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Coquina Oil Corporation

Address of Operator

P. O. Drawer 2960, Midland, Texas 79702

Location of Well

UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM

THE East LINE, SECTION 10 TOWNSHIP 24S RANGE 34E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

Alexander

9. Well No.

1

10. Field and Pool, or Wildcat

Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)

3583' KB

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is uneconomical and no further remedial work or completion attempts are contemplated. It is proposed that the 7 5/8" casing be pulled at its free-point and cement plugs placed in the well at the following depths.

Plug No.	No. Sacks	
1	75 sxs.	11,900' (Across top of liner, perforations, & 7 5/8" shoe)
2	75 sxs.	Across 7 5/8" casing stub.
3	75 sacks	Across any open hole interval in excess of 1500'
4	75 sacks	Across 10 3/4" casing shoe
5	25 sacks	Surface

The plugs will be spotted thru open ended tubing and the wellbore between plugs will be loaded with mud type fluid. See attached wellbore diagram. The wellbore will be cut off and a dry hole marker installed. Notice will be given so that all plugs may be witnessed.

100 PLUG @ 1500'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steve Guley

TITLE Production Engineer

DATE June 23, 1981

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Alexander # 1

