

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company	8. Farm or Lease Name W. B. Guthrie
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 3
4. Location of Well UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>23S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Jalmit Yates 7Rivers
15. Elevation (Show whether DF, RT, GR, etc.) 3380.6' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU, install BOP & POH w/compl assy. Set RBP @ 3640' & pkr @ 3410'. Acidize 7R 3505-3612' w/500 gals 15% NEFE. Swab back & test. Reset RBP @ 3450', dump sd on top. Perf Yates 7R @ 3082, 94, 3110, 21, 56, 75, 3200, 09, 14, 31, 72, 87, 3351 & 3425' w/1 JSPF. Set pkr @ 3000' & acidize Yates 7R 3082-3425' w/1000 gals 15% NEFE. Swab back load & test. Frac Yates 3082-3425' w/30,000 gals 70 quality foam w/63,122# sd. Flow back load. POH w/pkr, circ sd, CO & rec RBP. RIH w/compl assy & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elizabeth S. Bush

TITLE Drlg. Engr.

DATE 7/8/85

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: