STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

or Pas timitetimes De		
(07:11 HEEEIVER		
DISTRIBUTION		
SANTA FE		
FILE	I	
U.S.O.S.	Ĭ	
LAND OFFICE		
OPERATOR	-	

DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

UIL CONSERVATION DIVISION

P. O. HOX 2088

Form C-103

SANTA FE		SANTA FE, NEW MEXICO 87501				Revised 10-1-78
FILE				Г	5a. Indicate Type	e of Lease
U.\$.O.\$.					State	Fee X
OPERATOR				ŀ	5, State Off & Go	
SI	INDRY NOTICES	AND REPORTS ON	I WELLS		THITTHE	
(DO NOT USE THIS FORM F USE "AP	OR PROPOSALS TO DRIL PLICATION FOR PERMIT	L OR TO DEEPEN OR PLUG	BACK TO A DIFFERENT RES	ERVOIR.		
1.					7. Unit Agreemer	nt Name
WELL WELL	OTHER-	Commingled dowr	hole oil and g	as zones		
2. Name of Operator					8. Farm or Lease	
ARCO Oil and Gas Co	mpany, Divisi	on of Atlantic	Richfield Compa			teeler WN .
3. Address of Operator	1 - N - M	- 000/0		1	9. Well No.	c
P. O. Box 1710, Hob	bs, New Mexic	0 88240				5
4. Location of Well				þ	lo Field and Po Talmat Tans	ilf /R Yates
UNIT LETTERJ	. 1980 FEE	FROM THE South	LINE AND	FEET FROM	as Langlie	Mattix 7R On
				4		
THE East LINE.	SECTION	TOWNSHIP235	RANGE37	E		
minimize	mmm.	5 1 (61 1 1	DE BT CB		71111111	7//////////////////////////////////////
	//////////////////////////////////////	Elevation (Show whethe 3333.4			12. County	
			· 		Lea	<u> </u>
Ch.	eck Appropriate	Box To Indicate 1	Nature of Notice, F	leport or Othe	er Data	
NOTICE	OF INTENTION T	· O:	S	UBSEQUENT	REPORT OF:	
		_		f 1		<u></u>
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK	IXI		ING CASING
TEMPCRARILY ABANDON		(-)	COMMENCE DRILLING OF	7	PLUG A	AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEME	&PC TH		
		<u></u>	OTHER			U
OTHER	· · · · · · · · · · · · · · · · · · ·					
17. Describe Proposed or Comple	ted Operations (Clear	ly state all pertinent de	ails, and give pertinent o	dates, including e	stimated date of	starting any proposed
RU on 6/6/83, POH w	/rode & pmp	Installed ROP &	POH w/tho Ran	hit & ecra	mer to 380	Δ' PRD RIH
w/RBP & pkr, set RB						
acid. Swbd back &	rec 7 RIW in	hre Fraced	almat Cae norfe	2913-3112'	:2 w/±500 i	gals Pur-cel
25 & 20,000 gals CO	by wolume	carrying 84 000	of in 2 equal	stages F1	wd to nit	& cleaned.
up. Flwd Jalmat Gas	perfe 2 hre	on 3/4" of ARC	n 650 MCFCD RIH	w/retrivin	wu to pat '	c BOP @ 3255'
CO frac sd to 3805'	PRD RTH w/c	ON 3/4 CK ARC	ded 8 3793' s	et 2-3/8" t	ho @ 3444'	. Ran nmn
& rods. On 24 hr po						
6 BW, 600 MCFG, GOR						
o bu, ooo nere, ook	000,000.1. R	ecurned to proc	. IIou. piloi.	appront it	1101 00 111	THE THE OWNER
				•		
		•				•
			•			
-		• • • • • • • •				
•			()			√ Table 1
				-		
			·	•		
•	•	•	•	•		
* .						•
	•	•				•
					·	
18. I hereby certify that the inform	nation above 18 true a	nd complete to the best	of my knowledge and beli	ief.		
			7210 -			
BIGHED WILLIAM 1/	(wienes	TITLE	DKG ENG		DATE07/	/08/83
7 0 - 0						
ORIGINAL SIG	NED BY JERRY SEX	CTON			.111	1 1 2 1000

TUL 12 1983
HOBBS OFFICE

•