

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 1104	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS		8. Farm or Lease Name Lea "20", 7426 JV-S
3. Address of Operator 104 South Pecos Midland, Texas 79701		9. Well No. 2
4. Location of Well UNIT LETTER 'A' 330 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 26-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat Comanche Stateline (Tansill Yates S. Rive
15. Elevation (Show whether DF, RT, GR, etc.) 2937' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSED PROCEDURE:

Set CIBP @ 3100' Capped w/ 35' cmt.
Cut & pull 5½" csg. T.O.C. 2493'
40 sx cmt across 5½" stub - Tag Top of plug.
50 sx cmt across 8-5/8" shoe (shoe @ 1500') - Tag Top of plug.
10 sx @ Surface.

Install Dry Hole Marker

(9.5#/ gal Mud between plugs)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. R. Boyce BOYCE TITLE Administrative Supervisor DATE 11/15/82

ORIGINAL SIGNED BY

JERRY SEXTON

APPROVED BY DISTRICT 1 SUPER.
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NOV 18 1982