

Submit 3 Copies

to Appropriate

District Office

DISTRICT I

PO Box 1980, Hobbs, NM 88241-1980

DISTRICT II

PO Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-27212
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Whitten
8. Well No. 1
9. Pool name or Wildcat Jalmar Tansill Yates & River

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Primal Energy Corporation	
3. Address of Operator 222 Pennbriant, Suite 116, Houston, TX 77090	
4. Well Location Unit Letter F 1650 Feet From The North Line and 2310 Feet From The West Line Section 33 Township 23S Range 36E NMPM Lea County	
10 Elevation (Show whether DF, RKB, RT, GR, etc.) 3415.5'GR	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST & CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POOH with rods, pump and tubing.
2. Set CIBP @ 3190' with 20' cement cap. Circulate hole with 10 ppg mud.
3. Set cement plug from 1400' to 1200' using 25 sx.
4. Set cement plug from 100' to surface using 10 sx.
5. Install marker in top of well.

NOTE: Work performed on 8-5-97.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John Abernethy TITLE Manager, Operations & Engineering DATE 8/14/97
TYPE OR PRINT NAME John Abernethy TELEPHONE NO. 281-875-5100

(This space for State Use)

APPROVED BY Charles Perrin TITLE Director DATE 8/14/97
CONDITIONS OF APPROVAL IF ANY: