Form 3160-5 (November 1983) (Formerly 9-3.1)	DEPARTME OF THE INTERBUREAU OF LAND MANAGEME		ATE Ex	orm approved.  idget Bureau No.  spires August 31.  DESIGNATION AND	1085
EIGH ARD, DOU OATS	DRY NOTICES AND REPORTS form for proposals to drill or to deepen or plu Use "APPLICATION FOR PERMIT—" for such	ON WELLS g back to a different reservoir. proposals.)	6. IF IN	M. 19447 Idian, allottre or	TRIBE NAME
OH. WELL X WELL  2. NAME OF OPERATOR	OTHER 30	-025-27557	7. UNIT	AGREEMENT NAME	
Tempo Ener	<u> </u>	<del></del>	ľ	OR LEASE NAME	
3. ADDRESS OF OPERATOR	8) 3 100		EXX	kon Federal	
4000 N. Bi 1. LOCATION OF WELL (R See also space 17 belo At surface	g Spring, Suite 104 Midland eport location clearly and in accordance with as w)	, Texas 79702 or State requirements.*	10. FIEL	1 D AND POOL, OR WILL th-Mason De	
			11. SEC.	11. SEC., T., R., M., OR BLE. AND SURVEY OR ARMA	
L 1750 FS	L & 400 FWL West  15 ELEVATIONS (Show whether	DF. RT, GR. etc.)	Sec.		East
16	CL LA			EA	M
N	Check Appropriate Box To Indicate of Intention to:	Nature of Notice, Report,	or Other Dat	la .	
TEST WATER SHUT-OF	· · · · · · · · · · · · · · · · · · ·	S	BSEQUENT REPOR	T OF:	
FRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPUETE	WATER SHUT-OFF		BEPAIRING WELL	
SHOOT OR ACIDIZE	ABANDON*	FRACTURE TREATMENT SHOUTING OR ACIDIZING		ALTERING CASING	7
REPAIR WELL	CHANGE PLANS	(Other)		ABANDONMENT*	
17. DESCRIBE PROTUSED OR proposed work. If nent to this work.) •	complete operation (Clearly state all perting well is directionally drilled, give subsurface loc  Plug # 1 Set 4-1/2" CIBP	ent details, and give pertinent actions and measured and true	dates, including vertical depths fo	or an markers and	
08/26/91	Plug # 2 Circ. hole w/10.5	<pre>0 4400 Capped w/5   0 MLF From 4300' -  </pre>	SXS Cement		
08/26/91	, _ , _ , _ ,	it 1439' could not	pull.		
08/27/91	Plug # 4	.492' W.O.C.	,		
08/28/91	Plug # 5 Tag top of plug a	t 1200†			
08/28/91 08/30/91	Plug # 6 Cut 4-1/2" Csg. a	it 848' Lay csg. do	wn.		
08/30/91	Plug # 7 Spot 40 SXS plug Plug # 8 RIH & Tag plug at	at 900 (50' inside	csg. stub	)	
08/30/91	Plug # 9 Spot 40 SXS Plug	from 300'-153'			
08/30/91	Plug # 10 Spot 14 SXS Plug	from 50' to surf.		SEP CAI ARI	
	Install dry hole marker.			3 - 1	20
	install dry hole marker.			٠	TT1
				က	C C
				် ပြ	EIVE
					E
					_
				ω <sub>H</sub> <u>9</u>	
8. I hereby certify that the	e foregoing is true and correct				<del></del>
SIGNED		quisition Manager	DAT	rk Sept. 4,	1991
(This spage for Federa		en e			
APPROVED BYCONDITIONS OF APP	ROVAL, IF ANY:	2 2 2 3 3	DAT	nc 9/17/	9