

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-6135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Ralph E. Williamson	8. FARM OR LEASE NAME Wright Federal
3. ADDRESS OF OPERATOR P.O. Box 16 Midland, Texas 79702	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Double X Delaware
14. TERM OF WELL 1980 FNL & 1980 FEL	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 27 T-24-S, R-32-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3565.6' GR	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRAC TURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRAC TURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE FINISHED OR COMPLETED OPERATIONS* (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 3-26-851. Set CIBP @ 4850' and put 35' of cement on same.
3-37-852. Cut off 4 1/2" casing @ 3911' and pull same.
3-38-853. Set 100' cement plug 50' in and out of 4 1/2" stub, 35 sx tagged plug, plug held.
4. Set 100' cement plug from 2750-2850' to isolate salt, plug need not be tagged (35sx)
5. Set 100' cement plug from 1085-985' in and out of end of 3 5/8" casing. (35sx)
Tried to tag plug after 2 hrs. (plugg did set, held weight).
6. Set second 35 sx plug, plug held. Plug tagged after 4 hrs., held weight.
7. Set 50' surface plug
8. Erected dry hole marker.

(All plugging procedures were witnessed and approved by BLM representative on location)

18. I hereby certify that the foregoing is true and correct

SIGNED

Kala R. Schmidt

TITLE

Agent

DATE

04-01-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

*See Instructions on Reverse Side

RECEIVED

APR - 3 1985
RECEIVED

APR - 3 1985
FBI

U.S. DEPT. OF JUSTICE
HOBBS OFFICE