

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☐ well ☐ other ☐ DRY HOLE

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P.O. Box 728, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit Ltr. F, 1980 FNL & 1980 FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☐
☐
☐
☐
☐
☒

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIBP at 3150' and spot 35' cmt. on top of plug.
2. Spot 100' (15 sx) cmt. plug from 2200-2100'.
3. Spot 100' (15 sx) cmt. plug from 1500-1400'.
4. Spot 100' (15 sx) cmt. plug from 1000'-900'.
5. Spot 100' (15 sx) cmt. plug from 50'-surface.
6. Install dry hole marker and clean location. P&A.

Received verbal approval to P&A, 11/84.

Work completed 11/24/84.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED MA Bahner TITLE Dist.Opr. Mgr. DATE 5/31/85

APPROVED BY Orig. Sgd. Charles S. Dutton (This space for Federal or State office use)

CONDITIONS OF APPROVAL, IF ANY: _____ TITLE _____ DATE _____

JUN 2 1985

Received
AUG 14 1966
S. C. S.
Armed Forces Office