

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
P. O. BOX 1960
HOBBS, NEW MEXICO 88240

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☐ DRY HOLE ☐

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P.O. Box 728, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
 AT SURFACE: Unit Ltr. F, 1980 FNL & 1980 FWL
 AT TOP PROD. INTERVAL:
 AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>
(other)	

SUBSEQUENT REPORT OF:

RECEIVED
JUN 06 1985
FBI - NEW YORK

5. LEASE

LC-030181 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H.G. Moberly Federal (a)

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

Langlie Mattix (7-Rivers Grayburg)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 8, T-26S, R-37E

12. COUNTY OR PARISH | 13. STATE

Lea	NM
-----	----

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
2973' (GR)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIBP at 3150' and spot 35' cmt. on top of plug.
2. Spot 100' (15 sx) cmt. plug from 2200-2100'.
3. Spot 100' (15 sx) cmt. plug from 1500-1400'.
4. Spot 100' (15 sx) cmt. plug from 1000-900'.
5. Spot 100' (15 sx) cmt. plug from 50'-surface.
6. Install dry hole marker and clean location. P&A.

Received verbal approval to P & A, 11/84.

Work completed 11/24/84.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W. Bahr TITLE Dist. Opr. Mgr. DATE 5/31/85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE 7/1/80