Form 9-331 (May 1963)	DEPAR	UNITED STATE TMENT OF THE		SUBMITCINCTRIPLICA (Other fustructions on verse side)	TE• re-	Budg		l. 1 No. 42-R1424. Nd Serial No.	
	GEOLOGICAL SURVEY					NM 2593			
(Do not		DTICES AND REP posals to drill or to deepe lICATION FOR PERMIT-				6. IF INDIAN,	ALLOTTEE	OR TRIBE NAME	
1. OIL WELL X CAS WELL OTHER Plugback						7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR						8. FARM OR LEASE NAME Ed Powell IG Federal			
Yates Petroleum Corporation 3. ADDRESS OF OPERATOR						9. WELL NO.			
207 South 4th St., Artesia, NM 88210						2			
4. LOCATION OF See also spa	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)						10. FIELD AND POOL, OR WILDCAT		
At surface	220 7977 6 2	00 		• <i>a</i>		South Leonard Queen			
	330 FNL & 3	30 FWL, Sec. 18-	-T26S-R38E			11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA			
			1. S.			Unit D.	Sec. 1	8-26S-38E	
14. PERMIT NO.		15. ELEVATIONS (Show		R, etc.)		12. COUNTY OF			
		3005	GR		Į	Lea		NM	
16.	Check .	Appropriate Box To li	ndicate Natur	e of Notice, Report,	or Of	her Data			
	NOTICE OF IN		1			NT REPORT OF	:		
TEST WATE	R SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF		REF	AIRING WE		
FRACTURE 7	REAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	X		ERING CAS		
SHOOT OR A	CIDIZE	ABANDON*		SHOOTING OR ACIDIZING	X		NDONMENT		
REPAIR WEI	-L	CHANGE PLANS		(Other) Perfora				X X	
(Other)	DOSED OF COMPLETED	OPERATIONS (Closely state	ll postinent det	(Note: Report re Completion or Rec	comple	tion Report and	Log forn	1.)	
nent of th	13 WOIR.)	OPERATIONS (Clearly state ectionally drilled, give subs							
oles. Set il or gas. 3, 54, 55, cid. Flowe IH and peri IH w/tubing /1500 gallo	packer at 39 POOH. WIH 59, 60, 61, ed and swabbe Forated 3617- g and test br ons 15% acid a 5000# 20/40 sa	350' w/35' cemer 58'. Acidized w and perforated 4 69, 70 and 71'. d. No oil or ga 24' w/7 .41" hol idge plug. Set and 6 ball seale and. Run tubing	7/1000 gal 145-71' w RIH. Ac as. POOH es as fol packer at ers. POOH	lons 15% NEFE a /12 .41" holes idized perfs 41 and set CIBP at lows: 3617, 18 3569'. Acidiz and frac'd w/2	cid. as f 45-7 400 , 20 ed p 0000	Swabbe ollows: /1' w/100)0' w/35'), 21, 22 perforati) gallons	d dry. 4145, 0 gall cémen , 23, ons 36 gelle	No 46, 47, ons 15% t on top. and 24'. 17-24' d 2% KCL	
		-					•		
	•								
-									
	416- 41-4 4h- 4	g is true and correct							

SIGNED LUCANTE DO MITT	TITLE Production Supervisor	DATE5-11-84
(This space for Federal or State office use) APPROVED BY	TITLE	DATE

*See Instructions on Reverse Side

٠

Carlelad, NEW MEXICO

RECEIVED MAY 2 2 1984 HOBBS OFFICE

ş