

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions  
reverse side)

Form approved  
Budget Bureau No. 1004-0115  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
Southland Royalty Company

3. ADDRESS OF OPERATOR  
21 Desta Drive, Midland, Texas 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1980' FSL & 1980' FWL, Sec. 30, T-24-S, R-34-E

14. PERMIT NO. 30-025-28873 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3536.4' GR

5. LEASE DESIGNATION AND SERIAL NO.

NM-28881

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Vaca Ridge "30" Fed Com

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Pitchfork Ranch (Morrow)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 30, T-24-S, R-34-E

12. COUNTY OR PARISH 13. STATE

Lea

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) Temporary Abandon

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.\*

1. MIRU CU. Load tbq w/brine. NDWH & NU BOP. Rise pkr & POH, LD tbq.
2. RU wireline & set 5 1/2" CIBP @ 14,700'.
3. Load hole w/10# brine & shut in until approval to plug the well is received.

The above was discussed on 11/14/85 with Bob Pitschke.

18. I hereby certify that the foregoing is true and correct

SIGNED

Lawrence Robert

TITLE

Operations Engineer

DATE

11/14/85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

11-14-85

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side