

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
MEXICO

SUBMIT IN TRI-CATE
(Other Instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

6. LEASE DESIGNATION AND SERIAL NO

NM-28181

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

N.E. Salado Draw (Deep)

8. FARM OR LEASE NAME

N.E. Salado Draw (Deep)

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wolfcamp N.E. Salado Draw

11. SEC., T., R., M., OR BLK. AND
SUBST. OR AREA

Sec. 6 T26S R34E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
BP Exploration Inc.

3. ADDRESS OF OPERATOR
P. O. Box 4587 Houston, TX 77210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Letter E, 1980' FNL & 660' FWL
±19 miles WSW of JAL, N.M.

14. PERMIT NO.
NM-28181

15. ELEVATIONS (Show whether DF, BT, GR, etc.)
3319.8'

12. COUNTY OR PARISH
Lea

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

101N

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

No.	SX Cement	Depth (Ft)	Marker
1)	185 SX	Retainer @ 13000' Squeeze cement below retainer, spot 100' on top	Wolfcamp 9-5/8" casing shoe
2)	45 SX	7" Casing Stub, Tag Plug	100' above/below cut
3)	30 SX	9800-9900'	Bonesprings L.S.
4)	30 SX	6800-6900'	Brushy Canyon
5)	60 SX	5150-5350', Tag Plug	13-3/8" Casing Shoe
6)	55 SX	Perf. 9-5/8" @ 850', Squeeze below retainer; 100' on top of retainer	Salt
7)	10 SX	Surface Plug	

18. I hereby certify that the foregoing is true and correct

SIGNED

H. J. Dupuy

TITLE

Prod. Oper. Sup't.

DATE

10-23-89

(This space for Federal or State office use)

Orig. Signed by [Signature]

APPROVED BY

TITLE

PETROLEUM ENGINEER

DATE

11-7-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side