

New Mexico Oil and Gas
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NM 19861

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Madera 33 Fed Com #3

9. API Well No.

30-025-29836

10. Field and Pool, or Exploratory Area

Pitchfork Ranch (Atoka)

11. County or Parish, State

Lea NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

EOG Resources Inc.

3a. Address

P.O. Box 2267 Midland, Texas 79702

3b. Phone No. (include area code)

915 686 3689

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 33, T-24-S, R-34-E
660' FWL & 1980' FSL

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

9/20/02 Pumped 30 sx cement down 2 7/8" tbg into 3 1/2" liner to set plug in 3 1/2" liner.
Witnessed by Steve Caffey -BLM. POH. WOC.

9/21/02 RIH w/ 2 7/8" tbg and tagged cement plug @ 12968'. Mix mud laden fluid.
Spot 20 sx cement plug from 12968'-12838'. POH to 9400'.
Spot 30 sx cement plug from 9400'-9200'. POH to 5718'.

9/24/02 RIH w/ jet cutter and cut 5 1/2" casing @ 6500'. Attempted to pull, unsuccessfully.
RIH w/ jet cutter and cut 5 1/2" casing @ 5175'. POH w/ 80 jts. 5 1/2" casing.

9/25/02 RIH and spot 25 sx cement plug from 6550'-6450'. POH. WOC. RIH w/ 2 7/8" tbg.
Tagged plug @ 6325'. POH to 5225'. Spot 50 sx cement plug from 5225'-5125'. POH. WOC.

9/26/02 RIH w/ 2 7/8" tbg. Tagged plug @ 5105'. POH to 2700'. Spot 35 sx cement plug from 2700'-2600'.
POH to 1200'. Spot 35 sx cement plug from 1200'-1100'. POH to 675'.
Spot 35 sx cement plug from 675'-575'. POH to spot surface plug. Spot 10 sx cement surface
plug. Cut off wellhead and weld on P&A marker.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Stan Wagner

Title

Reg Analyst

Date 9/26/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.