

Perforations: con't

3293'-95', 3310'-15', 3318'-21'

33 3155'-61', 3163'-65', 3171'-75', 3177'-80',
3064'-70', 3072'-75', 3079'-85', 3103'-08', 3111'-14',
3123'-25', 3127'-29', 3132'-34',
2902'-04', 06', 08', 10', 13', 15', 17', 2929'-21', 23', 30',
31', 32', 47', 49', 51', 53', 55', 57', 59', 61', 63', 65',
67', 69', 91', 93', 94', 95', 96', 97', 98', 3002'-02', 04',
06', 08', 10', 12', 13', 27', 28', 29', 32', 33', 43', 35',
37', 38', 39', 42', 43', 44', & 3045',
3310-15, & 3318-21.

3355' :

16 BBL 15% HCL-NE-FE acid w/10% xylene

150 BBL "

24 BBL TFW

100 BBL TFW (Swab)

3190'-3150'

1 BBL 15% HCL-NE-FE

3155'-3180' :

50 BBL acid w/10% xylene

21 BBL TFW

3135'-3050' :

2 BBL 15% HCL-NE-FE ~~300~~

3064'-3134' :

75 BBL 15% HCL-NE-FE acid w/10% xylene

18 BBL TFW

2902'-3045' :

6 BBL 15% HCL-NE-FE acid w/10% xylene

14 "

441/ 125 "

"

"

RECEIVED

RECEIVED
MAR 5 1989
OCE
HOBBS OFFICE