

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30 025 30483

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil / Gas Lease No.

596800

7. Lease Name or Unit Agreement Name

SIMS, R. R. "A"

8. Well No.

1

9. Pool Name or Wildcat

NORTH TEAGUE WOLFCAMP

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter N : 330 Feet From The S Line and 2308 Feet From The W Line
Section 4 Township 23S Range 37E NMPM Lea COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3317' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: FRAC W/FOAMED ACID ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-23-99: MIRU. RU KILL TRUCK. KILL W/2% KCL. NDWH. NUBOP. REL PKR.
12-28-99: TIH W/BIT, CSG SCRAPER, TBG TO 7135'. STOP BIT @ 2488'.
12-29-99: UNLOAD, RACK, TALLY FRAC TBG. TIH W/FRAC PKR, SN. TEST TBG TO 4753'. TEST TO 8500 PSI.
12-30-99: NDBOP. NU FRAC TREE. SET PKR @ 7133'. TEST TREE TO 8000 PSI. LOAD/PSI CSG TO 500-OK.
1-04-00: ACID FRAC WOLFCAMP PERFS 7246-7312' W/5000 GALS 20% NEFE ACID & 50,000 GALS 20% FOAM ACID. PUMP AS FOLLOWS: 5000 GALS 20% NEFE, 5000 GALS WF-130 PAD, 20000 GALS 20% NEFE FOAM ACID, 10000 GALS WF-130 FOAM PAD, 20000 GALS 20% NEFE FOAM ACID, 10000 WF-130 FOAM PAD, 10000 GALS FOAM ACID, FLSH W/3780 GALS WF-130.
1-05-00: RU SWAB.
1-06-00: FL @ 3800'. END FL @ 4500'. KILL W/2% KCL. ND FRAC TREE. NUBOP. REL PKR.
1-07-00: TIH W/PKR, SN, TBG. TEST TO 5000 PSI. LEFT PKR SWING @ 7127'.
1-10-00: DISPL W/235 BBLs PKR FLUID. NDBOP. SET PKR @ 7127'. NUWH. LOAD & CHART CSG TO 500# FOR 30 MINS-OK. FL @ 700'. END FL @ 3000'.
1-11-00: FL @ 2400'. END FL @ 4600'.
1-12-00: RIG DOWN. HU PLUNGER LIFT.
1-14-00: FISH PLUNGER. RUN TBG BROACH & FOUND TITE SPOT IN TBG @ 3500'.
2-07-00: COULD NOT CATCH PLUNGER. RU SWAB. UNFLANGE WH & INSTL BOP.
2-08-00: KILL TBG W/20 BBLs 2% KCL. TIH W/MUD JT, SN, IPC JT, TAC & TBG. SN @ 7320'. NDBOP. SET TAC. NUWH.
2-15-00: MOVED OFF ROTO-FLEX & SET 640 UNIT.
2-19-00: PU 1 1/4" PUMP & RECONDITIONED STRING OF RDS.
2-25-00: ON 24 HR OPT. PUMPED 15 BO, 19 BW, & 84 MCF. PERFS 7246-7312 WOLFCAMP.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 3/7/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE