Form 3160-5 [Newtember 1983) (Formerly 9-331) DEPAR BUR	SUBMIT IN TRI .CATE. RIOR (Other instructions on re-	5. LEASE DESIGNATION AND SERIAL NO.		
SUNDRY NO (Do not use this form for proceed use "APPI")	C. JARM OR LEASE NAME			
OIL GAS WELL OTHER				
Highland Production				
	Suite 202 Odosso To	707/1	9. Wall No.	<u>Federal</u>
4. LOCATION OF WELL (Report location See also space 17 below.) At surface 990' FSL and	Suite 202, Odessa, Tex on clearly and in accordance with an	y State requirements.*	North Mason 11. SEC., T., E., M., OI SURVEY OF ARI Section 18,	(Delaware)
14. PERMIZ NO.	15. ELEVATIONS (Show whether p	F, RT, GR, etc.)	R-32-E, NMP	M
16.	3195' GR		دم آ	New Mexico
Check	Appropriate Box To Indicate 1	Nature of Notice, Report, or C	ther Data	- MON HEATE
NOTICE OF INTENTION TO: SUBSEQUE TEST WATER SHCT-OFF PULL OR ALTER CASING			ENT REPORT OF:	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	MULTIPLE COMPLETE ABANDON® CHANGE PLANS	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Drill & Com (Note: Report results Completion or Recomple it details, and give pertinent dates, tions and measured and true vertical	of multiple completion	mation X
7/14/90 Spud 3:15 P 7/15/90 Set 8 5/8" s 7/19/90 Ran 5 1/2" p Circulate to 8/2/90 Logged well. 8/7/90 Rig up cable 8/8/90 Ran tubing to	M urface casing at 1130 roduction casing. Set 895'. tool. o 4238'. with 6800 gals. bil and	' with 600 sacks cement t at 4326', set with 7		
18. I hereby certify that the foregoing	1975	SEP (17 199)		
SIGNED MARVIN L. Smith (This space for Federal or State of	MILL TITLE P	resident	DATE August	30, 1990
APPROVED BY	MYMY D		DATE	

*See Instructions on Reverse Side