

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30 025 31200

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil / Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

HARRISON, B.F. "B"

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

8. Well No.

4

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

9. Pool Name or Wildcat

Teague Drinkard Abo North

4. Well Location

Unit Letter D : 660 Feet From The NORTH Line and 800 Feet From The WEST Line

Section 9 Township 23S Range 37E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3318, KB-3336

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ Recomplete to Abo/Drinkard ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-04-99: (ABO ZONE) MIRU.PERF CSG IN ABO FORMATION FR 6606-7098'.
2-05-99: TIH W/FRAC PKR ON FRAC TBG. TEST TO 8500#. PSA 6494'. NDBOP. NU FRAC TREE. TEST BACKSIDE TO 1000#-OK.
2-06-99: ACIDIZE ABO PERFS 6606-7098' W/4000 GALS 15% NEFE HCL. FLSH TO BTM PERF W/70 BBLS 2% KCL WTR. RU SWAB. FL @ SURF. END FL @ 2600'.
2-08-99: ACID FRAC ABO PERFS 6606-7098' W/15,000 GALS 65 QUAL C02 FOAM 20% HCL ACID. TEST OVERNIGHT.
2-09-99: TIH W/PLUG & SET IN SN @ 6484'. BLED DN TBG. ND FRAC TREE. NU BOP. UNSET PKR. SWAB TBG DN TO 6000'. LD TBG & PKR. C/O RAMS IN BOP. TIH W/PKR, SN, ON TBG TO 3100'.
2-10-99: KILL WELL W/40 BBLS 2% KCL WTR. TIH W/2 7/8" TBG. SET PKR @ 6566'. SN @ 6565'. KB 18'. NDBOP. NU 5K TREE. DUMP 30 BBLS 2% W/COR INHIB DN BACKSIDE. PRESS TEST PKR & CSG TO 540# FOR 30 MIN-OK. RAN CHART. FL @ 1800'. SWAB TO 2500'.
2-12-99: RIG DOWN. OPEN WELL UP. FLOW & CHECK FOR C02. SWITCH WELL TO PRODUCTION STAC/PAC.
2-18-99: FLOW ON FULL OPEN CHOKE. FL @ 5500'. LEFT WELL OPEN TO BTRY.
3-01-99: (DRINKARD ZONE) PUMP 30 BBLS 2% KCL WTR TO KILL TBG. ND TREE. NUBOP. REL PKR & TOH W/TBG.
3-02-99: KILL W/30 BBLS 2% KCL WTR. TIH W/CIBP & SET @ 6540'. TIH W/2 7/8" TBG OPEN ENDED TO 6530'. CIRC HLE W/150 BBLS 2% KCL WTR. TEST & CHART CIBP TO 520# FOR 30 MINS-OK. TIH W/CSG GUN & PERF DRINKARD FORMATION FR 6335-6493'.
3-03-99: UNLOAD & RACK 3 1/2" FRAC TBG. TIH W/MIL-COR FRAC PKR, SN ON FRAC TBG. TEST TO 8000#. PSA 6233'. NDBOP. NU FRAC TREE. TEST TREE TO 8000#. LOAD & TEST BACKSIDE TO 800#-OK.
3-04-99: PRESS BACKSIDE TO 500#. ACIDIZE DRINKARD PERFS 6335-6493' W/3000 GALS 15% NEFE HCL. RU SWAB. FL @ 2400'.
3-05-99: ACID FRAC DRINKARD PERFS 6335-6493' W/10,000 GALS 65 QUAL C02 FOAM 20% HCL. FLOWBACK ON 10/64.
3-06-99: TIH W/PLUG & SET IN SN @ 6226'. BLED OFF TBG. NDTREE. NUBOP. REL PKR. TIH W/PKR, SN, & 2 7/8" TBG. PSA 6284'. NDBOP & NU 5K TREE. LOAD & TEST-CHART BACKSIDE TO 500#-OK.
3-07/08-99: RU SWAB. FL @ 1000'. END FL @ 1500'. RU SWAB. FL @ 400'. END FL @ 3800'.
3-15-99: KILL WELL W/30 BBLS 2% KCL. NDTREE. NUBOP. REL PKR. TIH W/BIT, DC'S & TBG TO 5655'.
3-16-99: TAG CIBP @ 6540'. DRILL UP CIBP. PSH TO 7300'. TIH W/OPSMA, SN, & TBG. TBG @ 7137'. SN @ 7103'. NDBOP. SET TAC.
3-17-99: TIH W/GAS ANCHOR, SNKR BARS, RDS. LOAD & TEST TO 500#-OK. RIG DOWN.
3-30-99: ON 24 HR OPT. PUMPED 31 BO, 27 BW, & 216 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 4/13/99

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: