

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 31538
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	SIMS, R. R. "A"
8. Well No.	2
9. Pool Name or Wildcat	TEAGUE SAN ANDRES NORTH
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3320' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>N</u> : <u>660</u> Feet From The <u>S</u> Line and <u>1650</u> Feet From The <u>W</u> Line Section <u>4</u> Township <u>23S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3320' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TA ABO, DRK, RECOMPLETE IN SAN ANDRES ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-01-00: MIRU. UNSET PMP. NDWH. NUBOP.
12-04-00: TIH W/BIT & CSG SCRAPER ON TBG TO 6505'. TIH W/CIBP & SET @ 6450'. TA DRINKARD/ABO. TIH W/CMT BAILER & DUMP 35' CMT ON CIBP. NEW PBD @ 3415'. TIH W/TBG OPEN ENDED TO 6380'. TEST & CHART CSG TO 500# FOR 30 MIN - OK. PULL TBG TO 6300'.
12-05-00: TIH & RUN USIT LOG 6400-2500.
12-06-00: TIH W/PERF GUN & PERF SAN ANDRES 3938-3952, 3900-4004. TIH W/SONIC HAMMER TOOL, & SN ON TBG TO 3900'.
12-07-00: ACID WASH PERFS IN SAN ANDRES FORMATION 3935-4004' W/2000 GALS 15% NEFE HCL. RU SWAB. FL @ SURF. END FL @ 1800'.
12-08-00: SWAB DRY. TIH W/TBG. LEFT KILL STRING @ 1500'.
12-11-00: KILL W/30 BBLs 2% KCL WTR. TIH W/SN, TBG, & TAC. SN @ 4030'. TAC @ 3903'. NDBOP. NUWH. TIH W/STRAINER NPPL, PMP & RDS. HUNG ON. LOAD & TEST TO 500#-OK.
12-12-00: RIG DOWN.
1-24-01: ON 24 HR OPT. PUMPED 10 BO, 45 BW, & 7 MCF. SAN ANDRES PERFS 3938-4004.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/16/01
TYPE OR PRINT NAME J. Denise Leake PAUL F. KAUTZ Telephone No. 397-0405
PETROLEUM ENGINEER

(This space for State Use)

APPROVED _____ DATE _____
CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____

MAR 26 2002

2A w Teague Drinkard Abo

