Form C-103 Revised 1-1-89

Submit 3 copies to Appropriate

v, Minerals and Natural Resources Department

District Office							U	eviseu 1-1-03
DISTRICT I	OII	CONSERV	/ATIO	N DIVISI	ON F	WELL API NO.		· · · · · · · · · · · · · · · · · · ·
P.O. Box 1980, Hobbs, NM						WELL AFTINO.	30 025 31538	
P.O. Box 2088 Santa Fe, New Mexico 87504-2088					ŀ	5. Indicate Type of Lease		
P.O. Box Drawer DD, Artesi	ia, NM 88210	Santa Fe, New	iviexico	8/504-2088	ŀ	o. Indicate Typ	STATE	FEE 🗸
DISTRICT III					ŀ	6. State Oil / G		<u>-</u>
1000 Rio Brazos Rd., Azteo						and the second of the	7	97
S JNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.						7. Lease Name or Unit Agreement Name SIMS, R. R. "A"		
1. Type of Well: OIL WELL	GAS — WELL —	OTHER						
2. Name of Operator	TEXACO EXPLORA	TION & PRODUCTI	ON INC.			8. Well No.	2	
3. Address of Operator	205 E. Bender, HOE	3BS, NM 88240				9. Pool Name TE	or Wildcat AGUE SAN ANDRES NO	RTH
4. Well Location								
Unit Letter	N:660	Feet From The	eS	Line and 165	0	Feet From	The W Line	e
Section 4	Towr	iship 23S	R	ange 37E	NMF	PM	LEA COU	NTY
	10. E	Elevation (Show whethe	r DF, RKB,	RT,GR, etc.) 33:	20' GR			
11.	Check Approp	riate Box to Indic	ate Nati	ure of Notice, R	Report,	or Other D	ata	
NOTICE OF	INTENTION TO):			SU	BSEQUE	NT REPORT OF	·.
PERFORM REMEDIAL WOR		AND ABANDON	-	REMEDIAL WORK		<u>~</u>	ALTERING CASING	
TEMPORARILY ABANDON		GE PLANS	=	COMMENCE DRILL	ING OPE	RATION	PLUG AND ABANDON	MENT ==
PULL OR ALTER CASING				CASING TEST AND	CEMENT	JOB		
OTHER:				OTHER:		RE-ACI	DIZE PERFS	<u> </u>
12. Describe Proposed or Oproposed work) SEE R 1-02-01: MIRU. NDWH. N 1-03-01: ACIDIZSE SAN A 1-04-01: FL @ 1200'. SW 1-05-01: TIH W/SN OPEN LOAD & TEST TO 500#-0 1-08-01: REPLACED SAE 1-24-01: ON 24 HR OPT. FINAL REPORT	JLE 1103. JUBOP. TIH W/PKR, 1 ANDRES PERFS 393 AB DRY. REL PKR. ENDED, TBG, TAC. DK. PUMPING @ 1:00 DDLE BEARING & RE	SN ON TBG. SET P. 8-4004' W/5000 GA SN @ 4034'. TAC @ PM. RIG DOWN. ETURN TO TESTING	KR @ 384 LS 15% N @ 3908'. N	0'. LOAD & TEST EFE HCL. RU SW	BACKSII IAB. FL @	DE TO 500#-) SURF. ENI	-OK. D FL @ 3000'.	
I hereby certify that the information above	is true and complete to the best	at my knowledge and belief.						
SIGNATURE CALL	yense-	* Xakiffile	Engin	eering Assistar	nt		DATE 2/16/0	1
TYPE OR PRINT NAME	J. Denis	e Leake					Telephone No. 39	7-0405

(This space for State Use) APPROVED