Submit 3 copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico

Form C-103 Revised 1-1-89

Eı رم, Minerals and Natural Resources Department

DISTRICT				Trevised 1-1-03
DISTRICT I	OIL CONSERVATION	ON DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			30 025 32223	
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease		
DISTRICT III			STATE	FEE [
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELL				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement	Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			SIMS, G. W.	
1. Type of Well: OIL GAS GAS				
WELL WELL OTHER				
2. Name of Operator			8. Well No.	
TEXACO EXPLORATION & PRODUCTION INC.				
3. Address of Operator P.O. Box 46510, Denver Colorado 80201-6510			9. Pool Name or Wildcat	
4. Well Location				
Unit Letter B : 510 Feet From The NORTH Line and 2230 Feet From The EAST Line				
Section 9 Township 23-S Range 37-E NMPM LEA COUNTY				
Coulon S				
	10. Elevation (Show whether DF, RKB,	RT,GR, etc.) GR-3310',	KB-3324'	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTIO			JBSEQUENT REPORT	OF
_	PLUG AND ABANDON		-	
PERFORM REMEDIAL WORK	<u> </u>	REMEDIAL WORK	ALTERING CASIN	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPE	=	DONMENT
PULL OR ALTER CASING		CASING TEST AND CEMEN	_	
OTHER:	Ц	OTHER: C	OMPLETION - ABO/DRINKARD/TUB	BB 🖂
 MIRU POOL WELL SERVICE. KILL WELL & SET BPV IN BO2 COUPLING. ND TREE & NU BOP. RELEASE PACKER & TOH. TIH W/ RETRIEVING TOOL ON 2.875" TBG TO 6274". WASH SAND TO RBP @ 6344". RELEASE RBP & TOH TO 5100". SET RBP & TEST TO 1500 PSI. ND BOP. NU DUAL HANGER SPOOL& BOP. CLOSE RAMS & TEST HANGER SEAL TO 1500 PSI. RELEASE RBP @ 5100" & TOH LAYING DOWN 2.875" TBG. CLOSE BLINDS & CHANGE PIPE RAMS TO 2-1/16" RAMS. RU UNION WIRELINE & TIH W/ 2-1/16" WIRELINE RE-ENTRY GUIDE, 1-JT OF 2-1/16", 1.43" TYPE "R" PROFILE NIPPLE W/ 1.385" NO GO, 1-JT OF 2-1/16", X O, MILLOUT EXTENSION & GUIBERSON 5.5", 17#, "HT" MAGNUM DRILLABLE PACKER TO 6060" & SET SAME. TIH W/ 2-3/8" "XL" ON/OFF TOOL W/ 1/43 TYPE "F" PROFILE 2.375" X 2.063" X O & LATCH SEAL ASSEMBLY TO 2800". 11-30-94. TIH W/ 2-1/16" LT, LATCH ONTO PKR. PKR SET @ 6060". TOP TUBB PERF @ 6098". 12-01-94. REMOVE BPV FROM LT HANGER. RU PRO WL & RETRIEVE PLUG FROM PROFILE NIPPLE. RELEASE FROM PKR VIA SEAL ASSEMBLY & TOH STANDING BACK W-2-1/16" TBG. PICK UP 4.5" MILLOVER SHOE DRESSED W/ 4.75" CUT RIGHT, PACKER PICKER, BUMPER SUB, JARS, 6-3.5 DCS ON 2.875" TBG. TIH TO 1000". 12-02-94. FINISH TIH W/ MILLOVER SHOE. MILL SLIPS ON MAGNUM PKR & START TOH. SHUT DOWN. LEAVE PKR HANGING 4770". 12-03-94. FINISH TOH & RECOVER MAGNUM PKR. TIH/TOH LDTBG & DC'S. RU UNION WL & RUN IN HOLE W/ 5.5" MAGNUM PKR. STUCK PKR @ 5867". PULL 70% OF ROPE SOCKET & FREE PKR. TOH & LD PKR. 12-04-94. TIH ON WL, 4635" GUAGE RING & JUNK BASKET TO 6950". POOH & RECOVER SMALL CHUNK OF RUBBER. TOH W/ AN ORECOVERY. TIH W/ 2-1/16" WLRG, 1-JNT OF 2-1/16" TBG, 1.43" TYPE "F" PROFILE, 2.375" X 2.063" X O & LATCH SEAL ASSEMBLY ON 2.063", 3.25#, J-55, J1 10 RND TBG TO THE TOP OF PKR. CIRCULATE TBG CAPACITY 2.5 TIMES IN REVERSE. LATCH INTO KR. SET WL. SET BPV IN PKR PROFILE & TEST TO 1500 PSI. RELEASE FROM PKR & SPACE OUT TO LEAVE IN NEUTRAL TENSION. LATCH INTO KR. SET WL. SET BPV IN PKR PROFILE & TEST TO 1500 PSI. RELEASE FROM PKR & SPA				
hereby certify that the information above is true and complete SIGNATURE <u>C.P. Bashba</u>	Can SRH TITLE Drilling	ng Operations Mgr.	DATE	1/13/95 (303)621-4851
TYPE OR PRINT NAME	C. P. Basham		, ciopitolio (10.	(555)521-551
(This space for State Use)	SEXYON		Ja	# £ 3 1395
APPROVED BY	GETT SALES STATES		DATE	<u> </u>

RECEIVED

144 2 6 1995 1 122 40888 08810**8**