

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32226
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	DAVIS, F. B.
8. Well No.	1
9. Pool Name or Wildcat	Teague Lwr Pad/Blinbry/Tubb/Drk/Abo Assoc
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3323', KB-3337'

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter A : 660 Feet From The NORTH Line and 500 Feet From The EAST Line

Section 8 Township 23-S Range 37-E NMPM LEA COUNTY

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ Recomplete in Blinbry, Acid Frac

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-05-99: MIRU. TIH W/PARAFFIN KNIFE & CUT 25" PARAFFIN.
10-06-99: KILL WELL. TIH W/BIT, CSG SCRAPER ON TBG TO 6062'. TIH W/PERF GUN & PERF BLINEBTY FORMATION FR 5554-60, 5594-5600, 5606-12, 5654-56, 5662-64, 5698-5702, 5730-32, 5746-48, 5780-86, 5834-36, 5858-60. TIH W/RBP, & PKR, SN, ON TBG. TEST TO 5000#. SET RBP @ 6010'. PULL UP & SET PKR 6808'. TEST RBP TO 1000#-OK. DUMP 2 SX SAND DN TBG. PULL UP & SET PKR @ 5452'.
10-07-99: LOAD & TEST BACKSIDE TO 800#-OK. ACIDIZE BLINBRY PERFS 5554-5860 W/4000 GALS 15% NEFE HCL. RU SWAB. FL @ SURF. SWAB DRY. RD SWAB. REL PKR & LOWER TO 5900'.
10-08-99: UNLOAD, RACK, TALLY FRAC TBG. TIH W/FRAC PKR, SN. PU & TEST TBG TO 8000 PSI. WELL FLOWING. TEST TBG IN HLE TO 5436'.
10-09-99: PU FRAC TREE. CIRC CSG. SET PKR @ 5436'. PSI CSG TO 1000 PSI-OK.
10-12-99: FRAC TREAT BLINBRY PERFS 5554-5860 W/16,800 GALS YF-140, 60,522 GALS YF-140.
10-13-99: TIH W/SNKR BAR TO 5430'. NO SAND., ND TREE. REL PKR @ 5436'. CHANGE RAMS ON BOP. TIH W/BIT & BAILER & TBG TO 5464'.
10-14-99: LOWR TBG & TAG @ 5851'. C/O FRAC SAND TO 6012'. BAILER QUIT. TIH W/BIT, BAILER, & TBG. TAG @ 5937'. C/O TO 6012'. PULL BIT TO 5496'.
10-15-99: C/O W/BAILER TO RBP @ 6012'. C/O OUT 50' FRAC SAND. TIH W/PKR, SN, & TBG. PSA 5528'. NDBOP. NUWH. TEST CSG & PKR TO 500# & CHART FOR 30 MINS-OK. RU SWAB. FL @ SURF.
10-16-99: HOOK UP TO FLOWLINE. FLOWING TO BATTERY @ 9:30 AM.
10-18-99: SI WELL TO WORK ON TANK BATTERY. RIG DOWN.
10-23-99: ON 24 HR OPT. FLOWING 191 BO, 0 BW, & 1005 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 11/04/1999

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

ORIGINAL SIGNED BY

GARY WINK

APPROVED BY FIELD REP. II

TITLE

DATE NOV 30 1999

CONDITIONS OF APPROVAL, IF ANY:

2A Teague Drinkard Abo