<b>61</b> 10 2 10 10	State of New Mexico	Form C-103	
Submit 3 copies to Appropriate District Office	gy, Minerals and Natural Resources Department	Revised 1-1-89	
DISTRICT I	OIL CONSERVATION DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088	30 025 32226	
DISTRICT II	Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease	
P.O. Box Drawer DD, Artesia, NM 88210		STATE FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil / Gas Lease No.	
UND RID BIZZOS KU., AZLEC, NM 57410 SUNDRY NO (DO NOT USE THIS FORM FOR PRO DIFFERENT RESE (FORM	7. Lease Name or Unit Agreement Name F.B. Davis		
1. Type of Well: OIL GAS WELL WE			
2. Name of Operator TEXACO EX	8. Well No. 1		
3. Address of Operator P.O. BOX 7	9. Pool Name or Wildcat		
4. Well Location		- Automation	
Unit LetterA:	660 Feet From The <u>N</u> Line and 500	Feet From TheELine	
Section 8	Township Z3S Range 37E Ni	MPM Lea_ COUNTY	
	10. Elevation (Show whether DF, RKB, RT,GR, etc.) GR-3323	, КВ-3337	
11. Check A	Appropriate Box to Indicate Nature of Notice, Report	rt, or Other Data	
NOTICE OF INTENTI		UBSEQUENT REPORT OF:	
_			
PERFORM REMEDIAL WORK		ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME Drinkard zone OTHER:	ALTERING CASING Image: Constraint of the second	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK   CHANGE PLANS COMMENCE DRILLING OF   CASING TEST AND CEME   Drinkard zone OTHER:   Derations (Clearly state all pertinent details, and give pertinent dates)	ALTERING CASING Image: Constraint of the second	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME Drinkard zone OTHER:	ALTERING CASING Image: Constraint of the second	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME Drinkard zone OTHER: perations (Clearly state all pertinent details, and give pertinent dates new well and TOH.	ALTERING CASING Image: Constraint of the second	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME Drinkard zone OTHER: perations (Clearly state all pertinent details, and give pertinent dates new well and TOH. bg and set at +6480'. TOH. +6450'. Test RBP to	ALTERING CASING Image: Constraint of the second	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS Drinkard zone Drinkard zon	ALTERING CASING Image: Constraint of the second	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Derations (Clearly state all pertinent details, and give pertinent dates new well and TOH. bg and set at +6480'. TOH. +6450'. Test RBP to to 1000 psi. Install fflare gas. If sales line	ALTERING CASING Image: Constraint of the second	

I hereby certify that the information shove is true and com	plete to the best of my knowledge and t	TITLE	Engr Asst	DATI	E
	Larry W. Johnson			Telephone	No. 397-0426
(This space for State Use)			ORIGINAL SIGNED BY JERRY SEXTON		MAR 03 1994
APPROVED BY		TITLE_	DISTRICT I SUPERVISOR	DATE_	
CONDITIONS OF APPROVAL, IF ANY:				DeSot	ofNichols 12-93 ver 1.0

## **RECEIVED**

DOD HOBBS