

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 32369	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil / Gas Lease No. B-1732-1	
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT	
8. Well No. 124	
9. Pool Name or Wildcat DOLLARHIDE TUBB DRINKARD	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter C : 300 Feet From The NORTH Line and 1350 Feet From The WEST Line
Section 4 Township 25-S Range 38-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3162', KB-3173'

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Acidize & Scale Squeeze <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/11/00: MIRU. NDWH. NUBOP. TAG UP @ 6880'.
8/14/00: TIH W/SONIC HAMMER TOOL ON 190 JTS 2 7/8" STOP @ 6240'.
8/15/00: ACID WASH DRINKARD PERFS 6250-6890 W/4000 GALS 15% NEFE HCL & 193 BBLS 2% KCL WTR. SCALE SQUEEZE SAME PERFS W/165 GALS TH-756 MIXED IN 100 BBLS 2% KCL WTR & FLSH W/115 BBLS 2% KCL WTR.
8/16/00: TIH W/BPMA, TBG, TAC. TBG @ 6859. SN @ 6832, TAC @ 6180. NDBOP. NUWH. TIH W/GAS ANCHOR, PUMP, SINKER BARS, & RDS. TEST TBG TO 500#-OK. HUNG ON. RIG DOWN. GOING @ 5:00 PM
9/26/00: ON 24 HR OPT. PUMPED 20 BO, 142 BW, & 22 MCF.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant

DATE 9/18/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY TITLE

DATE