

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32369
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1732-1
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	124
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

SUNDY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>C</u> : <u>300</u> Feet From The <u>NORTH</u> Line and <u>1350</u> Feet From The <u>WEST</u> Line Section <u>4</u> Township <u>25-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3162', KB-3173'
--	--------------------

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/> Acidize & Scale Squeeze

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-23-99: MIRU. UNHUNG WELL & BUMPED PUMP LOOSE. POH W/RDS & PMP. UNFLANGE WELL & UNSET TAC. NU BOP & TAG DN @ 6927'.
2-24-99: TIH W/SONIC HAMMER TOOL & ACIDIZE ERFS W/3000 GALS 15% NEFE. RU SWAB & SWAB BACK LOAD. TIH W/TBG & TAC.
2-25-99: BLED DN WELL. TIH W/TBG & SET TAC & NDBOP. TIH W/2 7/8" TBG, TAC, SN & MUD JT. TAC @ 6171'. SN @ 6825'. TBG @ 6854'. TIH
W/PMP, GAS ANCHOR, SNKR BARS, & RDS. HANG ON & LOAD & TEST. RIG DOWN.
3-06-99: SCALE SQUEEZE W/3 DRUMS TH793
3-10-99: ON 24 HR OPT. PUMPING 24 BO, 129 BW, & 21 MCF. GOR-875. PERFS 6252-6890' ABO, TUBB, DRINKARD
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 3/18/99
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]
CONDITIONS OF APPROVAL, IF ANY: