

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32496
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	HARRISON, B. F. 'B'
8. Well No.	15
9. Pool Name or Wildcat	Drinkard- TEAGUE NORTHWEST, DEVONIAN Abo
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3326', KB-3338'

SUNDY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
P.O. Box 46510, Denver Colorado 80201-6510

4. Well Location
Unit Letter P 500 Feet From The SOUTH Line and 500 Feet From The EAST Line
Section 5 Township 23-S Range 37-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETION - ABO/DRINKARD/TUBB ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRUSU. TOH W/ TBG AND PLUNGER. TIH W/ 2-7/8' WORKSTRNG TO 4000'. 02-01-95.
- CLEAN OUT SAND TO TOP OF RBP @ 6297'. TIH. RELEASE RBP AND TOH. TIH TO 1600'. 02-03-95
- TOH. LD 2-7/8" TBG. TIH W/ PKR AND SET @ 1500'. INSTALL VALVE AND TEST ANNULUS TO 1000#. ND BOP AND INSTALL DUAL ADAPTER SPOOL TO TBG SPOOL. NU BOP. REL PKR AND TOH. 02-03-95.
- RU UNION WL AND TIH W. PKR TO 6300' AND SET. LATCH INTO PKR. PRO WL. SET PLUG IN PKR PROFILE. REL F/ PKR AND SPOT PKR FLUID. SPACE OUT AND LAND LONG TBG IN HANGER. PRESSURE TEST TBG TO 1500 PSI. INSTALL BPV IN LT COUPLING. START IN HOLE W/ 2-1/16" UT. 02-04-95.
- INSTALL BPV IN UT AND PACK OFF. ND BOP, NU TREE AND TEST TREE SEAL TO 3000 PSI. REMOVE BPV'S FROM LT & UT. RETRIEVE PLUG F/ PKR PROFILE AND START SWABBING LT. 02-05-95. SW UT 2 BO, 18 BW IN 1.5 HRS. FL 6 BO, 48 BW IN 3.5 HR 02-15-95.
- PUT ON PLUNGER LIFT ON 02-15-95.
- DROP PLUNGER ON UT AND START PRODUCING TO BTTRY. 02-16-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham TITLE Drilling Operations Mgr. DATE 2/23/95
TYPE OR PRINT NAME C. P. Basham Telephone No. (303)621-4851

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 14 1995

CONDITIONS OF APPROVAL, IF ANY: