

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32499
5. Indicate Type of Lease	STATE ☐ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	HARRISON, B. F. 'B'
8. Well No.	25
9. Pool Name or Wildcat	TEAGUE LOWER PADDOCK BLINEBRY, N. ASSOC

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>C</u> : <u>825</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>9</u> Township <u>23-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3313'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: Acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-07-99: MIRU. NDWH. NUBOP. TIH W/BIT, CSG SCRAPER ON TBG TO 5422'.
 9-08-99: CONTINUE TIH TO 6360'. TIH W/SONIC HAMMER TOOL & SN ON TBG. ACID WASH TUBB PERFS 6084-6234' W/3500 GALS 15% NEFE HCL. TBG @ 6242'. RU SWAB. FL @ 5000'. END FL @ 6200'.
 9-09-99: TIH W/CCL/GR LOG FR 5950-5500'. TIH W/PERF GUN & PERF CSG IN BLINEBRY FORMATION FR 5590-94,5670-74,5692-94,5711-17, 5747,5754-56, 5804-06, 5822-24, 5838-40. TIH W/RBP & PKR. SET RBP @ 6000'. PKR @ 5998'. PULL RBP & PKR ABOVE PERFS.
 9-10-99: TIH W/RBP, PKR, SN & TBG. SET RBP @ 6000'. PKR @ 5998'. NO TEST. MOVE RBP TO 5985'. PKR TO 5980'. NO TEST. TEST IN HOLE W/PKR TO 5000 PSI. SET PKR @ 5980'. TEST RBP TO 1000-OK. RAISE & SET OJR @ 5502'. LOAD & PSI CSG TO 800-OK. ACIDIZE BLINEBRY PERFS 5590-5840 W/4000 GALS 15% NEFE ACID.
 9-11-99: TIH W/7" PKR, & SN. PU & TEST 3 1/2" TBG TO 8000 PSI. NDBOP. NU FRAC TREE. LOAD & PSI CSG TO 1000 PSI-OK. PSA 5486'.
 9-13-99: FRAC PERFS 5590-5840, W/13,985 GALS YF-135 D PAD.
 9-14-99: TIH W/WASH TIP. BREAK CIRC. C/O SAND FR SURF TO 5560'. ND FRAC TREE. NUBOP. REL PKR. TIH W/USED BIT ON TBG TO 5430'. MIRU REV UNIT & FOAM UNIT.
 9-15-99: LOWER TBG & TAG FILL @ 5562'. C/O FRAC SD TO RBP @ 5985'. PULL BIT TO 5493'.
 9-16-99: TAG SD FILL IN CSG @ 5963'. RU SWAB. FL @ 2900'. TIH W/KILL STRING TO 1954'.
 9-17-99: TIH W/PERF GUN. RE-PERF CSG IN BLINEBRY FR 5589,91,93,95,5669,71,73,75,91,93,95,5710,12,16,18,46,48,53,55,57,5803,05,07,21,23,25,37,39,41. TIH W/FRAC PKR, & SN. FRAC TBG TEST TO 8000#. NDBOP. NU FRA TREE. PSA 5489'. LOAD & TEST BACKSIDE TO 1000#-OK.
 9-20-99: ACIDIZE BLINEBRY CSG PERFS 5589-5841' W/3500 GALS 15% NEFE HCL. DO MINI FRAC W/10,000 GALS 40# X-LINK GEL. STEP RATE 1 BPM TO 35 BPM. PRESS FR 1500#-4330#. FRAC SAME PERFS W/44,000 GALS 40# X-LNK GEL.
 9-21-99: TIH W/SNKR BAR ON SD LINE. TAG BELOW PKR @ 5550'. ND FRAC TREE-NU BOP. REL PKR. TIH W/BIT & BAILER ON TBG. TAG BRIDGE @ 5565'. FELL THRU. LOWER TOOLS & TAG SD @ 5774'. C/O TO 5870'.
 9-22-99: C/O SD W/BAILER TO 5905'. TIH W/SAME TOOLS & TAG @ 5905'. C/O CSG TO RBP @ 5985'. TIH W/TAC, SN & TBG. NDBOP. NUWH. TAC @ 5532'. SN @ 5531'. RU SWAB. FL @ 900'. HOOK UP TO FLOWLINE. 9-24-99: RIG DOWN. WELL ON TEST.
 9-28-99: ON 24 HR OPT. FLOWING 100 BO, 145 BW, & 1149 MCF. (BLINEBRY 5589-5841') FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 10/13/1999
 TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS

DISTRICT I SUPERVISOR APPROVED BY _____ TITLE _____ DATE NOV - 2 1999

CONDITIONS OF APPROVAL, IF ANY:

Shut-In N Torrance Tubh Assoc

