Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	nergy, Minerals and Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-32901
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco	STATE EX FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505		0. 5 5 5 5
SUNDRY NOTICES A (DO NOT USE THIS FORM FOR PROPOSALS TO	ND REPORTS ON WELLS DORILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		R.R. Sims "A"
1. Type of Well: Oil Well Gas Well	Other	
2. Name of Operator		8. Well No.
. Texaco Exploration & P	roduction, Inc.	8
3. Address of Operator P. O. Box 3109, Midlan	d. TX 79702	9. Pool name or Wildcat Teague,
4. Well Location	4, 11, 13, 102	Tubb, L. Paddock, Blinebry, Assoc.
· ·		
Unit Letter N : 660 feet from the South line and 1930 feet from the West line		
Section 4 Township 23-8 Range 37-E NMPM Lea County		
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENT		IBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLU	G AND ABANDON 💢 REMEDIAL WO	ORK ALTERING CASING
TEMPORARILY ABANDON CHA	NGE PLANS COMMENCE D	ORILLING OPNS. PLUG AND
	TIPLE CASING TEST CEMENT JOB	AND ABANDONMENT
OTHER:	OTHER:	П
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
orrecompilation. 1. Set 7" CIBP @ 5625'. spot 40 sx plug 5625'-5425' (Blinebry) WOC Tag		
 Set 7" CIBP @ 5625', spot 40 sx plug 5625'-5425' (Blinebry) WOC Tag Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL 		
3. Spot 40 sx plug 3500'-3300', (Queen) WOC Tag		
4. Spot 50 sx plug 3000'-2600' (Yates, B-Salt) WOC Tag		
5. Spot 40 sx plug 1300'-1100' (9 5/8" shoe, T-Salt) WOC Tag 6. 10 sx Surf plug, Install dry hole marker.		
o. To sk suit plug, install dry note marker.		
		DANGERON MUST BE HOMBED 24
		CALAR TO THE SECTIONS OF INC. OPERATIONS FOR THE C-103
		APPROVED.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE 7. Cord	litt TITLE FACILITY &	
	7 22	915 400 4120
Type or print name AMES 1. (DKB177	Telephone No. 688 - 4938
(This space for State use)	The State of the S	
APPPROVED BY	TITLE	DATE
Conditions of approval, if any:	3. 554	

JC

des