

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32901
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	R. R. SIMS 'A'
8. Well No.	8
9. Pool Name or Wildcat	N. Teague Tubb & Lwr Paddock Blinbry Assoc
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter N : 660 Feet From The SOUTH Line and 1930 Feet From The WEST Line
Section 4 Township 23-S Range 37-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	REPAIR CSG LEAK <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/10/00: MIRU. PUMP HUNG UP @ 3334'. WORK LOOSE. LD PUMP. CUT PARAFFIN TO 2400'.
7/11/00: PUMP 50 BBLs HOT WTR WS/Q10 GALS TF270 PARAFFIN SOLVENT DN TBG. RUN FP 3000-2500'. STUCK @ 2990'. FREE @ 2984'.
SET DOWN 3011'. TIH W/PARAFFIN KNIFE TO 2990'. TIH W/HAPPY TOOL ON RDS TO 3975'. TIH W/CHEM CUTTER & STOP @ 2184'. RUN
HAPPY TOOL TO 3975'.
7/12/00: CUT 30' PARAFFIN. LOWER TO 2980. C/O PARAFFIN. LOWER TO 5200'. RUN CHEM CUTTER & STOP @ 2995'. TIH W/JET CUTTER.
STOP @ 3013. RUN CHEM CUTTER. CUT TBG @ 2969'. TBG COLLAR @ 2984. INSTL BOP. NDBOP. INSTL TBG FLANGE. RD WL.
7/13/00: TIH W/RDS. RIG DOWN. WELL TO BE P&A. SHUT IN. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake*

TITLE Engineering Assistant

DATE 8/22/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE