Form C-103

State of New Mexico Submit 3 copies to Appropriate Enc. gy, Minerals and Natural Resources Department District Office Revised 1-1-89 DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-32901 DISTRICT II Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Box Drawer DD, Artesia, NM 88210 FEE [STATE 🔀 DISTRICT III 6. State Oil / Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) R. R. SIMS 'A' OIL GAS 1. Type of Well: \boxtimes WELL WELL OTHER 2. Name of Operator 8. Well No. **TEXACO EXPLORATION & PRODUCTION INC** 3. Address of Operator 9. Pool Name or Wildcat P.O. Box 46510, Denver Colorado 80201-6510 4. Well Location 660 ___ Feet From The __SOUTH _Line and 1930 Feet From The WEST Line Township 23-S ___ Range <u>37-E</u> **NMPM** LEA COUNTY 10. Elevation (Show whether DF, RKB, RT,GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING CHANGE PLANS COMMENCE DRILLING OPERATION **TEMPORARILY ABANDON** PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB

OTHER:	based .		OTHER:	COMPLETION	[
12. Describ	be Proposed or Completed Operations (Clearly state all pertinen	t detai	is, and give	pertinent dates, including estimated date of starting any pr	oposed

- MIRU UNION WL AND PULLED GR-CCL FROM 7204-5800'. TIH. PERF'D THE ABO W/ 2 JSPF: 6694-6706', 6732-6738', 6868-6881', 6896-6900', 6906-6914', 6917-6942', 6964-6969', 6988-6992', 6996-7002', 7026-7029', 7041-7048', 7074-7092', 7116-7132'. 250 HOLES. 06-06-95.
- RU DOWELL AND ACIDIZED DN 7" CSG W/3,000 GALS 15% NEFE. ACID FRAC'D THE ABO W/ 30,000 GALS 55Q FOAMED ACID AND 47,000 GALS 30# LINEAR FOAMED PAD. 06-09-95.
- RU UNION WL. SET RBP @6614'. PERF'D THE DRINKARD W/ 2 JSPF: 6515-6536', 6541-6544', 6547-6563', 6591-6608'. 114 HOLES.TIH W/ PKR.
- RU DOWELL AND ACIDIZED THE DRINKARD W/ 1,800 GALS 15% NEFE. FRAC'D DN 3.5" TBG/40# BORATE XL GEL. PUMPED 7500# 100 MESH SD IN PAD. FRAC'D WELL W/ 50,549# 20/40 ECONOPROP, LAST 28,000# SD HAD PROPNET. 06-26-95.
- RU DOWELL. ACIDIZED THE DRINKARD PERFS W/ 3,000 GALS OF 15% HCL. 07-16-95.
- RU DOWELL AND ACID FRAC'D THE DRINKARD W/ 30,000 GALS 55Q FOAMED ACID, 47,000 GALS 30# LINEAR FOAMED PAD. 07-22-95.
- FINISHED TOH W/ PKR. TIH AND REL RBP. TOH. LD 2-7/8" TBG. RU UNION WL AND SET 7" CIBP @ 6500". UNION WL PERF'D THE TUBB W/ 2 JSPF: 6098-6104', 6121-6123', 6127-6134', 6140-6145', 6158-6164', 6182-6190', 6202-6214', 6222-6226', 6251-6254', 106 HOLES.08-05-95.
- TIH W/ NOTCHED COLLAR, SN ON 3.5" TBG. BOTTOM TBG @ 5990'. 08-06-95. 8
- RU DOWELL AND ACIDIZED THE TUBB W/ 2,000 GALS 15% NEFE. SAND FRAC W/ 56,000 GALS 40# BORATE XL GEL AND 190,000 20/40 OTTAWA SAND DOWN 3.5" TBG. LAST 35,000# OF SAND W/ PROPNET. 08-07-95.
- 10. DOWELL ACIDIZED PERFS: 6098-6254' W/ 10,000 GALS OF 15% HCL. 08-23-95. FLOWED 95 BLW ON 12/64" CK IN 4 HOURS.
- 11. HOOK UP PLUNGER LIFT EQUIPMENT. INSTALL AND TIE IN FLOW LINE. DROP PLUNGER. 09-03-95.
- 12. TIH W/ NOTCHED COLLAR, SN ON 3-1/2" TBG. 09-07-95.

work) SEE RULE 1103.

- 13. RU DOWELL. FRAC'D THE TUBB W/ 74,000 GALS OF 40# BORATE XLG AND 278,000# OF 20/40 OTTAWA SAND VIA 3.5" TBG. 09-09-95.
- 14. TIH AND TAG SAND@ 6380'. COS TO 6500'. TOH LAYING DOWN 3.5" TBG. 09-11-95.
- 15. TIH W/ PKR ON 2.875" TBG TO 5982' AND SET SAME. 09-12-95.

SIGNATURE C. P. Barlam SRH TITLE Drilling Operations Mgr.	
	DATE <u>11/10/95</u>
TYPE OR PRINT NAME C. P. Basham	Telephone No. (303)621-4851
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT LAGGERVISOR APPROVED BY TITLE	DATE NOV 16 1998