

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32944
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	SIMS, R. R. 'A'
8. Well No.	6
9. Pool Name or Wildcat	TEAGUE GLORIETA-UPPER PADDOCK.SW
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3324' GL, 3339' KB

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>M</u> : <u>500</u> Feet From The <u>SOUTH</u> Line and <u>375</u> Feet From The <u>WEST</u> Line Section <u>4</u> Township <u>23-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3324' GL, 3339' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ HORIZONTAL COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-14-00: MIRU KEY #330. NUBOP. REL TAC. TIH W/BIT & CSG SCRAPER TO 2800'. 8-16-00: TIH W/2 7/8" TBG TO 5430' (PBD). SET CIBP @ 5013'. TIH W/2 7/8" OPEN ENDED TO 5000'. 8-2-00: MIRU KEY #119. TIH W/MILLS & TAG CIBP @ 5013'. TAG CIBP @ 5018 (MD) TIH W/WHIPSTOCK TO 5000'. ORIENT WHIPSTOCK. SET WS/108 DEG AZIMUTH. TIH W/GYRO. MILL FR 5001-5002,5005,5007. TOW @ 5001, BOW @ 5007.RAN GYRO & SLIDE FR 5010-5037,5068,5121,5168,5210,5230,5240,5256,5280,5320,5332,5350,5362,5414,5427,5476,5496,5531. TD 4 3/4" HLE @ 1600 HRS 8-24-00. TIH W/SMITH WHIPSTOCK HOOK & JARS. CATCH WHIPSTOCK & JAR FREE. TIH W/RBP & SET @ 4901'. 8-26-00: REL RIG @ 0700 HRS 8-25-00
8-29-00: MIRU KEY #296. 8-30-00: TIH W/TBG TO 4901. TIH W/TBG TO 5032. COULD NOT GAG ON CIBP @ 5018. TIH W/SUB, PKR. TIH W/TBG TO 5032. ROTATED TBG & SET DOWN @ 5032. CIBP WLM @ 5013. 8-31-00: TIH W/TBG & TAG @ 5026' CIBP. TAG UP SAME AS 8-29-00, 5031', W/5' CORRECTION, OK. TIH W/TBG & TAG CIBP @ 5026. WENT INTO LATERAL HOLE. PU SUB, TBG, PKR, SN. TBG @ 5031'.SN @ 4912. PKR @ 4913. RIG DOWN KEY #296 9-01-00. 9-07-00: TIH W/COIL TBG. ACIDIZSE UPPER PADDOCK LATERAL OH W/6000 GALS 20% HCL 9-10-00: MIRU KEY #296. 9-12-00: REL PKR @ 4913. TIH ^ BUST UP CIBP @ 5013. PSH TO PBD @ 5431. TIH & SET CIBP @ 5095 WLM. PU PURGE VALVE, MA, SN, TBG, TAC. SN @ 5032, TAC @ 4967. 9-13-00: NDBOP. SET TAC @ 4967'. SN @ 5032. PU GAS ANCHOR, PMP, K-BARS, RDS.

1-25-01: MIRUSU. REM HORSES HEAD. LD RDS & PMP. 1-26-01: REL TAC. SET CIBP @ 4990'. TIH W/TBG & CIRC PKR FLUID. TEST CSG TO 600 PSI ON CHART FOR 30 MIN. 1-27-01: LD TBG. RAN USIT LOG FR 4990-1100. TIH W/CMT BAILER & DUMP 35' CMT ON CIBP @ 4990. PBD-4955. NDBOP. NUWH. RIG DOWN SERV UNIT.

FINAL REPORT - TEMPORARILY ABANDONED

This Approval of Temporary
Abandonment Expires 2/20/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/8/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF FIELD REPRESENTATIVE

ORIGINAL SIGNED BY GARY WINK TITLE FIELD REPRESENTATIVE II

DATE

FEB 21 2001

DeSoto/Nichols 12-93 ver 1.0

B/L = M, 338' FSL, 834' FWL, Section 4, T-23S, R-37E
339 835

JCGN

