

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals, and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION

TOP

BOTTOM

DESCRIPTION, CONTENTS, ETC.

38.

GEOLOGIC MARKERS

NAME

TOP
MEAS. DEPTH

TRUE
VERT. DEPTH

1080

1432

2750

2895

Rustler

Salado

Tansil

Uates