

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof: cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38.

GEOLOGIC MARKERS

| FORMATION | TOP | BOTTOM | DESCRIPTION, CONTENTS, ETC. | NAME | TOP | |
|-----------|-----|--------|-----------------------------|---------|-------------|------------------|
| | | | | | MEAS. DEPTH | TRUE VERT. DEPTH |
| | | | | Rustler | 1126 | |
| | | | | Salado | 1507 | |
| | | | | Tansil | 2704 | |
| | | | | Uates | 2902 | |

1995
Received
Hobbs
OCD