

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division

P.O. Box 1980

Hobbs, NM 88241

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

NM LC064118

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

RECEIVED

1991 MAY 12 P 10:09

SUBMIT IN TRIPLICATE

BUREAU OF LAND MGMT.  
ROSWELL OFFICE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

PLAINS PETROLEUM OPERATING COMPANY

3. Address and Telephone No.

415 W. Wall, Suite 1000 Midland, TX 79701 915/683-4434

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter I - 1650' FSL & 800' FEL  
Sec. 34, T23S, R37E

7. If Unit or QA, Agreement Designation

8. Well Name and No.

E. C. Hill "B" Federal #15

9. API Well No.

30-025-33475

10. Field and Pool, or Exploratory Area

TEAGUE BLINEBRY

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

ACCEPTED FOR RECORD

MAY 21 1997

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other

TYPE OF ACTION

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-28-97 Objective - Remove RBP & commingle Paddock & Blinebry Perfs. Unhang well, unseat PUP. Hot oil tbg & rods w/30 bbls oil. POOH w/rods & pump. Kill well w/50 bbls wtr. ND WH, NU BOP. Unset TAC, POOH w/tbg.

4-29-97 Pump 50 bbls wtr dwn csg. Open BOP, TIH w/retrieving head to 5230'. Wash frac balls off RBP, catch & release RBP. POOH w/RBP.

4-30-97 WIH w/166 jts 2-3/8" J55 EUE tbg (5220'), spaced out tbg & set TA w/12000# tension. PU & WIH w/ 20-150 RWBC 16-4 pump, 140- 3/4" sucker rods (3500'), 66- 7/8" sucker rods (1650'), 2- 7/8" pony rods (1-10' & 1-6', 16') & 1- 1-1/4" polish rod w/14' liner. EOT @ 5220', SN @ 5217.80', TAC @ 5029.80'. Hung well on & started pumping from commingled Paddock 5085'-5149' and Blinebry 5262'-5513' perforations.

5-2-97 All load has been recovered

one prod - see 5-10-96  
1-30-96

14. I hereby certify that the foregoing is true and correct

Signed Bonnie Husband

Title Admin. Assist

Date 5-08-97

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date \_\_\_\_\_

50

25 MAR 1977

PO BOX 15100 PM

RECEIVED  
30 APR 1977

