

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34148
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 21606

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name State 30
2. Name of Operator Cobra Oil & Gas Corporation	8. Well No. 1
3. Address of Operator P.O. Box 8206 Wichita Falls, Tx. 76307-8206	9. Pool name or Wildcat East Triste Draw-Atoka
4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>30</u> Township <u>24S</u> Range <u>33E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3546' gr</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/24/98 Rig up Schlumberger, run in hole with 2.1" bridge plug, stuck @ 14,615 Attempt to pump plug down, pump tools off rope socket, left 28.5' of tools including bridge plug in hole. Attempt to fish tools, top of tools @ 15,470'. Could not fish tools. Rig up Schlumberger, run in hole with 1.968" OD Baker CIBP, set @ 15,400'. Dump 27' of cement on top of bridge plug. Perf Atoka from 14,788'-14,795', 29 holes with 2 1/8" PDS, 60° phased Hollow Carrier, 4 SPF. Flow test well.

3/10/98 SWI for buildup. Prepare to plug back and test Wolfcamp.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rory Edwards TITLE Production Supervisor DATE 3/20/98
TYPE OR PRINT NAME Rory Edwards TELEPHONE NO. 940 716-5100

(This space for State Use) ORIGINAL SIGNED BY

GARY VINK

APPROVED BY FIELD REP. TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Not Posted
No production
2A Wildcat Maroon