

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34995
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	B F HARRISON "B"
8. Well No.	27
9. Pool Name or Wildcat	NORTH TEAGUE LWR PADDOCK BLINEBRY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3331'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER NEW DRILL
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>O</u> : <u>330</u> Feet From The <u>SOUTH</u> Line and <u>1650</u> Feet From The <u>EAST</u> Line Section <u>5</u> Township <u>23-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3331'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ SPUD & SURFACE CSG

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-19/8-11-00: SPUD 12 1/4" HLE @ 12:30 PM 7-18-00. 40' CONDUCTOR SET W/READY MIX CMT. DRLG 40-208,355,386,633,723,782,1200. RUN 29 JTS 8 5/8" 24# K-55 ST&C CSG 1200' KB SET @ 1200. CMT W/530 SX CL C W/4% D20, 2% SI. TAIL W/140 SX CL C W/2% SI8. CIRC 57 BBLS TO SURF. BUMP PLUG @ 11:53 AM. WOC 4 HRS. CUT OFF CSG. WELD ON 11X3000 SLIP ON HEAD. TEST TO 1500 PSI. NUBOP. TEST BOP. DRILL CMT & FLOAT EQPT. TAG CMT @ 1106. TEST CSG TO 1000 PSI-OK. DRILL 1217-1231,1355,1449,1574,1650,1700,1825,1950,2076,2105,2234,2272,2287,2295,2327,2390,2420,,2452,2470,2540,2545,2568,2576,2607,2670,2732,2740,2827,2921,3000,3380,3450,3565,3592,3624,3636,3658,3718,3812,3873,3957,4062,4155,4280,4310,4403,4528,4651,4665,4809,4841,5057,5115,5240,5396,5489,5620,5646,5756,5929,5937,6082,6333,6396,6427,6615,6710,6845,6845,6900,6994,7026,7031,7210,7274,7367,7460,7500,7555,7681,7750, TD 7 7/8" HLE @ 12 MIDNIGHT 8-07-00 @ 7750'.RUN FREEPOINT. PIPE STUCK @ 2023'.REAM 1370-1760, & 4785-5034. RUN PLATFORM EXPRESS NGT LOG TO 7750'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 8/12/00

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED 8/21/00 DATE 8/21/00

CONDITIONS OF APPROVAL, IF ANY: _____ TITLE _____ DATE _____