

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35028
5. Indicate Type of Lease	STATE FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	F.B. DAVIS
8. Well No	8
9. Pool Name or Wildcat	TEAGUE DRINKARD/ABO NORTH
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter B 960 Feet From The NORTH Line and 2245 Feet From The WEST Line Section 8 Township 23S Range 37E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPERATION	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER:		OTHER:	SPUD & SURFACE CSG <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-30-00/7-15-00: SPUD 12 1/4" HLE @ 3:30 PM 6-29-00. DRLD 58-182,292,399,664,782,806,960,1200 TD 12.25 HLE @ 6:00 PM 6-30-00. RUN 28 JTS 8 5/8" 24# K-55 ST&C CSG, 1200'KB, SET @ 1186'. CMT W/530 SX CL C W/4% GEL, 2% CACL2, TAILED W/140 SX CL C W/2% CACL2 CIRC 34 BBLS TO SURF OR 110 SX PLUG DN @ 1:00 AM 6-30-00. WOC 4 HRS. CUT OFF NUHEAD. WELD ON 11X3000 SLIP ON HEAD. TEST TO 1500#-OK NUBOP. ND BOP & SPOOL. NU SPOOL & BOP & TEST. PU BHA, BIT, MOTOR, X-O, DC'S. TIH & TAG CMT @ 1160. DRLD 4' CMT & FC @ 1161. DRLD 39' CMT & FLOAT SHOE @ 1200. DRLD 1200-1507,1538,1785,1972,2032,2157,2280,2404,2527,2559,2647,2772,3020,3142,3328,3575,3706,3864, 4111,4160,4359,4390,4483,4577,4632. TIH W/BIT. WASH & REAM 100' TO BTM. NO FILL. DRLD 4632-4671,4763,4887,4955,5012,5104,5258,5382 5720,5915,6127,6427,6520,6829,6953,7300, TD 7 7/8" HLE @ 5:45 AM 7-14-00. CIRC COND MUD. RAN PLATFORM EXPRESS, NGT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant  
TYPE OR PRINT NAME J. Denise Leake

DATE 7/16/00

Telephone No 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE