

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-35126	
5. Indicate Type of Lease STATE FEE ☒	
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name F.B. DAVIS	
8. Well No. 9	
9. Pool Name or Wildcat TEAGUE TUBB N. ASSCC	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	
3. Address of Operator 205 E. Bender, HOBBS, NM 88240	
4. Well Location Unit Letter <u>EF</u> <u>1680'</u> Feet From The <u>NORTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>8</u> Township <u>23-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3338'</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPERATION ☐
OTHER: ☐	CASING TEST AND CEMENT JOB ☐
	PLUG AND ABANDONMENT ☐
	OTHER: ☐
	PRODUCTION CASING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-19-01/4-20-01: RAN 5 1/2" CSG, 1 GUIDE SHOE, 2 SHOE JTS, L-80 17# 86.27', 1 FLOAT COLLAR, 1.15/21 JTS L-80 900.24' 1 MARKER JT L-80 22.53', 6 JTS L-80 255.03', 1 DV TOOL 2.20' 131 JTS K-55 17# 6034.93' TOTAL STRING = 7303.65'. DV TOOL @ 6019.81'. FC @ 7199.81'. RAN 6 CENTRALIZERS. WASH TO BOTTOM & CIRC 5 1/2" CSG. (161 JTS 5 1/2" CSG. CORRECTED TD BACK TO 7288 AS PER S.L.M. ON TRIP OUT FOR LOGGS.) CIRC 5 1/2" CSG. CMT 1ST STG W/400 SX 50/50 POZ. PLUS ADDITIVES. PLUG DOWN @ 8:15 AM 4-19-01. BUMP PLUG W/1535 P.S.I. PLUG HELD. OPEN DV TOOL. CIRC OUT 1ST STG CMT @ 6. BPM. CIRC OUT 81 SX CMT TO SURF. CMT 2ND STG W/ 1280 SX 35/65 POZ. DISPL W/140 8BLS FW. BUMP PLUG W/3456 P.S.I. @ 2:30 PM. PLUG HELD. NDBOP. SET SLIPS W/140 LBS ON SLIPS. NUWH. JET & CLEAN PITS. RIG REL @ 10:00 PM 4-19-01. RIG DOWN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/1/01

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED Paul Kautz Geologist DATE JUN 26 2001

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____ DATE _____