

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Altec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-35328

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
LG 4138

7. Lease Name or Unit Agreement Name

JACKSON UNIT

8. Well No. #8

9. Pool name or Wildcat  
JOHNSON RANCH WOLFCAMP

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator  
MURCHISON OIL & GAS, INC. 015363

3. Address of Operator  
1100 MIRA VISTA BLVD. PLANO, TX. 75093-4698

4. Well Location  
Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST

Section 22 Township 24S Range 33E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3591 GL 3612 KDB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING  
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud well @ 6:00 AM 3/28/01 with 17-1/2" bit and drill to 797'. Run 23 jts. of 13-3/8" 68# N-80 BUTT casing to 797'. Cement w/ 425 SXS of 35/65 POZ C + 6% D20 + 2% SI + .25 #/SX D29 followed by 200 SXS Class C + 2% SI + .25 #/SX D29. Circulate 179 SXS to reserve pit. Bumped plug, floats held. Cut off casing, weld on wellhead. Nipple up BOP's. Test blind rams and choke. Pick up BHA and test pipe rams. WOC 21 HRS. Drill out cement and plug. Resume drilling open hole with 12-1/4" bit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael S. Daugherty TITLE VICE PRESIDENT OPERATIONS DATE 4/3/01

TYPE OR PRINT NAME MICHAEL S. DAUGHERTY

(972)  
TELEPHONE NO. 931-070

(This space for State Use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

Paul Kautz  
Geologist

DATE

4/24/2001