

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35336
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	MEXICO L
8. Well No.	27
9. Pool Name or Wildcat	DOLLARHIDE FUSSELMAN
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3128'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109, MIDLAND, TX 79702
4. Well Location	Unit Letter <u>D</u> : <u>482</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>5</u> Township <u>25-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3128'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ FINAL TEST ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-17-01: MIRUSU. UNSEAT PUMP & TOH W/RDS. NUBOP.

7-18-01: TIH W/RBP & SET @ 8409'. TIH & DUMP BAIL 2' SAND ON TOP OF RBP. PERF FUSSELMAN FROM 8378-8398'. TIH W/1 JT TBG, PKR, & SN.

7-19-01: TIH W/2 7/8" TBG. TP @ 8351'. SET PKR @ 8320'. SPOT 5000 GALS 20% HCL TO 7500'. RU SWAB. FL @ 3000. NO OIL OR GAS. SLIGHT ACID GAS.

7-20-01: PBG PSI 50. TAG FLUID @ 2500. SWAB 3 HRS. FL @ 2500. REL PKR.

7-21-01: TIH W/TBG & BAILER TO 8405'. TIH W/RETR HEAD & TBG TO RBP @ 8409'. REL RBP.

7-22-01: TIH W/MUD JOINT ANCHOR, SN @ 8389, 2 7/8" TBG. SET TBG ANCHOR. NDBOP & INSTL LANDING FLANGE. TIH W/PMP, K-BARS & RDS. START UP WELL. PUMPING FROM BOTH UPPER & LOWER FUSSELMAN FORMATION. RDSU.

7-23-01/9-06-01: PUMPING AND TESTING.

9-07-01: ON 24 HR OPT. PUMPING 30 BO, 382 BW, & 8 MCF.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 9/24/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 915-688-4752

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE