State of New Mexico Form C-103 Submit 3 Copies , Minerals and Natural Resources Departmen Revised 1-1-52 to Appropriate Dinner Office OIL CONSERVATION DIVISION DISTRICT WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-35677 Santa Fe, New Mexico 87504-2088 DISTRICT IF 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NIA 88210 STATE X FEE DISTRICTIN 6. State Oil & Gu Lease No. 1000 Rio Britos Rd., A.nec., NM 87410 LG-3175 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: BRININSTOOL "4" STATE WELL 8. Well No. Name of Operator MURCHISON OIL & GAS, INC. 9. Pool name or Wildcat 3. Address of Operator WILDCAT 1100 MIRA VISTA BLVD. PLANO, TEXAS 75093-4698 4. Well Location 1890 WEST SOUTH 660 Foot From The Feet From The LEA County 24S **NMPM** Township Range Section 10. Elevation (Show whether DF, RKD, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Drilled 6" hole to a total depth of 13850'. Ran production liner as follows: Float shoc 2, Jts 4-1/2" 14.98 #/FT P110 Flush 58' 2 Float collar 1' 39 Jts 4-1/2" 14.98 #/FT P110 Flush 1502 Weatherford Liner Hanger 18' 1581' Top of Liner 12,271' Bottom of Liner @. 13,852 Cement w/ 240 SXS Class "H" + 1.7 GAL/SX D600 + .05 GAL/SX D047 + .15 GAL/SX D604AM + .3 GAL/SX D801 + .1% D153. Did not bump plug. Did not circulate any cement to surface. Set packer at top of liner and pull out of liner. TOH with liner hanger tool and TIH with bit and DC to drill cement on top of liner. Tag cement @ 11640 (629' of cement above liner). Drill out cement. Displace hole w/ 8.4 water. No pressure, liner top holding. Trip out of hole and lay down drill pipe. ND BOP's and jet pits. Release rig 10/28/01. d complete to the best of my knowledge and belief. VICE PRESIDENT OPERATIONS DATE _ SKINATURE. MICHAEL S DAUGHERTY TYPE OR PRINT HAVE

(This space for State Use)

ATTROVED BY-