| Form | 9-331 a |
|------|---------|
| (Feb | . 1951) |

Budget Bureau No. 42-R358.4. Approval expires 12-31-60.

| reb. 1 | 951) | • | | | Land Office | Las Cruces |
|----------|------|---|------------|----------------------------|-------------|-------------|
| | | | | (SUBMIT IN TRIPLICATE) | Lease No. | LC-061963-A |
| | | | | UNITED STATES | | |
| - | | | | DEPARTMENT OF THE INTERIOR | Unit | |
| | | | . . | GEOLOGICAL SURVEY | | |
| | | | X | | | |

SUNDRY NOTICES AND REPORTS ON WELLS

| NOTICE OF INTENTION TO DRILL | | SUBSEQUE | NT REPORT OF WATER | SHUT-OFF | 2 |
|--|-----------------------|--|---|--------------------|--------------|
| NOTICE OF INTENTION TO CHANGE PL | LANS | SUBSEQUE | NT REPORT OF SHOOTI | NG OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATE | ER SHUT-OFF | SUBSEQUE | NT REPORT OF ALTERI | NG CASING | |
| NOTICE OF INTENTION TO RE-DRILL | OR REPAIR WELL | SUBSEQUE | NT REPORT OF RE-DRIL | LING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR | ACIDIZE | SUBSEQUE | NT REPORT OF ABANDO | NMENT | |
| NOTICE OF INTENTION TO PULL OR A | LTER CASING | SUPPLEME | TARY WELL HISTORY | | |
| NOTICE OF INTENTION TO ABANDON | WELL | | | | |
| | TE ABOVE BY CHECK M | TRIACO In | RT, NOTICE, OR OTHER | 352 | . 19 |
| se No. 192741 F. Ray-Federal NCT-2 | | TELACO Ir Midland, | C., P.O. Box Texas | 352 February 14 | ·····, · / · |
| se No. 192741 F. Ray-Federal NCT-2 | | TELACO Ir Midland, | C., P.O. Box Texas | 352 February 14 | ·····, · / · |
| se No. 192741 | ed .330 ft. fr | $\frac{\mathbf{TRIACO} \mathbf{Ir}}{\mathbf{Midland}}$ | ro., P.O. Box Texas nd 330 ft.fro | 352 February 14 | ·····, · / · |
| se No. 1927[4] F. Ray-Federal MCT-2 /ell No. 1 is locate | ed 330 ft. fr | TELACO Ir Midland, | ro., P.O. Box Texas nd 330 ft.fro | 352 February 14 | ·····, · / · |
| 50 No. 192741 F. Ray-Federal MCT-2 /ell No. 1 is locate R/h SR/h, Sec. 9 (4 Sec. and Sec. No.) | ed 330 ft. fr | $\frac{\mathbf{TRIACO} \mathbf{Ir}}{\mathbf{Midland}}$ | ro., P.O. Box Texas nd 330 ft.fro | 352 February 14 | ·····, · / · |
| se No. 1927[4] F. Ray-Federal MCT-2 /ell No. 1 is locate | ed 330 ft. fr | TRIACO IF Midland, rom. ${S \atop S}$ line as | nd 330 ft. fro NMPN | 352 February 14 | ·····, · / · |

The elevation of the derrick floor above sea level is ft. available DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

20 - 331" Soudded 9-7/8" hele 1:30 P.M. February 10, 1961

Ran 318: of 7-5/8= 0.D. casing, 24:00 1b., H-40, 8-R, and comented at 331: with 250 ax Regular. Plug at 306'. Coment circulated. Job complete 7:30 P.M. February 10, 1961.

Tested 7-5/8" O.D. casing for 30 minutes with 1000 PSI from 7:30 to 8:00 P.H. February 11, 1961. Tested OK. Drilled cement plug and re-tested for 30 minutes with 1000 PSI from 10:00 to 10:30 P.M. February 11, 1961. Tested OK. Job complete 10:30 P.M. Pebruary 11, 1961.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TELACO Inc.

Address P.O. Box 352

Midland, Texas W. B. Hobbard

By MBILLan

Title Assistant District Superintendent