1. 2. 3. 4. 5. 6.

UNITED STATES DEPARTMENT OF THE INTERIOR

5.	LEASE	
	LC-061936 (A)	

	<u> </u>	1330			
æ	IF INDIAN	ALLOT	FEOR	TRIRE	NAM

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME		
The art use this form for proposals to drill or to deepen or plug back to a different	Cotton Draw Unit		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME		
1. oil gas	Cotton Draw Unit		
1. oil KK gas other	9. WELL NO.		
2. NAME OF OPERATOR	19		
TEXACO Inc.	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Paduca Delaware		
P. O. Box 728, Hobbs, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 5 5 8 8 6 6 6		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	$\stackrel{AREA}{\text{Sec.}} 10 \stackrel{?}{7} \stackrel{?}{1} \stackrel{?}{2} \stackrel{?}{2} 5 - S \stackrel{?}{7} \stackrel{?}{R} \stackrel{?}{5} \stackrel{?}{2} \stackrel{?}{2} \stackrel{?}{E}$		
below.)	12. COUNTY OR PARISH 13. STATE		
AT SURFACE: AT TOP PROD. INTERVAL: 660' FSL & 1980' FWL	Lea New Mexico		
AT TOTAL DEPTH: (Unit Letter 'N')	14. API NO. = 7-2 7. 00 27		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	eigh e Gogo		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
	3455' (DF)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	48		
FRACTURE TREAT			
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone		
REPAIR WELL U PULL OR ALTER CASING U	change on Form 9-330.)		
MULTIPLE COMPLETE	그 그 그 그 그 사람들이 가 불록됐었다.		
CHANGE ZONES			
ABANDON U (other) TO: CONVERT TO WATER INJECTION			
(other) TO: CONVERT TO WATER INJECTION			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent.	ILECTIONS IN CHINES, KINE BRESHINGCE LOCATIONS AND		
Rig up. Pull rods and pump. Install BC	OD Dull tubêndê		
Clean out.	or. ruii cubriigi.		
Set pkr @ 4660'. Acidize perfs 4704'-47	751' W/1000 aa P 15% NEFE Acid		
Run plastic coated injection tubing W/pk	or and set 0 4660'. 1		
Load Annulus W/inhibited water.			
Convert well to water injection.			
	보임 성류값 그는 그래를 수밖 그는		
	기육없을뿐 연형 공항한 중		
Subsurface Safety Valve: Manu. and Type	Set @ Ft.		
	~		
18. I hereby certify that the feregoing is true and correct			
SIGNED W.B. CLL TITLE Dist.Opr.M	19r. DATE		
(This space for Federal or State off	fice use)		
APPROVED BY TITLE	DATE 2-5-85		
CONDITIONS OF APPROVAL, IF ANY:			

*See Instructions on Reverse Side

RESEIVED

FFB -6 1985