Form approved.

(May 1963) DEPAF				
	OTICES AND REPORTS operals to drill or to deepen or plug LICATION FOR PERMIT—" for such			
1.			7. UNIT AGREEMENT NAME	
OIL X GAS WELL OTHER			Cotton Draw Unit	
2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
TEXACO INC.			Cotton Draw Unit	
3. ADDRESS OF OPERATOR			9. WELL NO.	
P. O. Box 728 - Hobbs, New Mexico 88240			19	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			Paduca Delaware	
660' FSL & 1980' FWL, Sec. 10, T-25-S, R-32-E			11. SEC., T., E., M., OR BLE, AND SURVEY OR AREA	
Lea County, New Mexico			Sec. 10, T-25	
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
Regular	3455' DF		Lea	New Mexic
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dir nent to this work.)*	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS OPERATIONS (Clearly state all pertine ectionally drilled, give subsurface locally drilled, give subsurface locally drilled)	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomp	DEPAIRING WALTERING CAABANDONMEN of multiple completion cetion Report and Log for including estimated data depths for all markers	on Well
REMARKS		a oal \ mala for Dow		
1. Well Status - Th	(-0 (To Be Recondition	ed-Oil) - Held for Rem	ediai work	
2. Temporary Abando	onment Date - 6-25-7	7		
3. Reason for Aband	lonment - Water break	through		
4. Future Plans -	Remedial work will b	e performed to return	well to product	ion
5. Date of Future V	Workover or Plugging -	4th Quarter, 1978		

*See Instructions on Reverse Signstrict ENGINEER TITLE Asst. Dist. Superintendent DATE 10-27-77 (This space for Federal or State office use)