

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	7. If Unit or CA, Agreement Designation Unit L
2. Name of Operator Texaco E&P, Inc.	8. Well Name and No. Cotton Draw Unit 41
3. Address and Telephone No. P. O. Box 3109 - Midland, TX 79702	9. API Well No. 30-02508179
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit L 1650' FSL, 660 FWL Sec-10 T-25S R32E	10. Field and Pool, or Exploratory Area Paduca Delaware
	11. County or Parish, State Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent <input type="checkbox"/> Subsequent Report <input type="checkbox"/> Final Abandonment Notice	<input checked="" type="checkbox"/> Abandonment <input type="checkbox"/> Recompletion <input type="checkbox"/> Plugging Back <input type="checkbox"/> Casing Repair <input type="checkbox"/> Altering Casing <input type="checkbox"/> Other	<input type="checkbox"/> Change of Plans <input type="checkbox"/> New Construction <input type="checkbox"/> Non-Routine Fracturing <input type="checkbox"/> Water Shut-Off <input type="checkbox"/> Conversion to Injection <input type="checkbox"/> Dispose Water <small>(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)</small>

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Notify BLM prior to plugging and abandonment of well.
2. TIH w/tub. CIBP @ 4495'. Circ. csg w/25# per Bbl. salt gel mud.
3. Spot 25 sx cmt plug f/4495'-4395'. (B-Salt 4432')
4. Perf. & sqz 1213' w/ pkr @ 1050' displace cmt to 1085'. WOC & tag. (Top of salt 1163')
5. POOH to 775'. Spot 25 sx cmt plug f/775'-675'. (Russler 775')
6. Perf. @ 450' & circ. cmt behind 5 1/2" casing to surface. Leave casing full of cement. Pump @ 165 sx of cement.
7. Nipple down BOP & cut off wellhead; cap well & install dry hole marker. Clean up location & move off.

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Operations Engineer Date 5/16/95
 (This space for Federal or State office use)
 Approved by Shannon J. Shaw Title Engineer Date _____
 Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side