

Submit 3 Copies
to Appropriate
District Office

Energy Minerals and Natural Resources Department

Form 100
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08197
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E 9789-1
7. Lease Name or Unit Agreement Name MONSANTO STATE
8. Well No. 2
9. Pool name or Wildcat PADUCA; DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator V-F PETROLEUM INC.	
3. Address of Operator P.O. BOX 1889, MIDLAND, TEXAS 79702	
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>16</u> Township <u>25-S</u> Range <u>32-E</u> NMMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP PLUGGING RIG.
2. PULL ALL RODS & TUBING.
3. SET CIBP @ 4,530'.
4. DUMP 35' CEMENT ON CIBP. - TAG
5. STRETCH CASING & SHOOT AT FREE POINT. (EST. @ 3,600') LAY DOWN CASING.
6. SPOT 100' CEMENT. PLUG 50' IN & 50' OUT OF STUB. WOC 4 HR. +.
7. TAG TOP OF PLUG.
8. SPOT 100' CEMENT PLUG 1,900' - 2,000'.
9. SPOT 100' CEMENT PLUG 300' - 400' (IN & OUT OF SURFACE CASING) WOC 4 HR. +.
10. TAG TOP OF CEMENT PLUG.
11. CUT OFF 10 3/4" x 5 1/2" WELLHEAD.
12. SPOT 10 SX CEMENT PLUG AT SURFACE.
13. INSTALL DRY HOLE MARKER.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Wayne Luna TITLE PRODUCTION SUPERINTENDENT DATE 11/03/01
TYPE OR PRINT NAME M. WAYNE LUNA TELEPHONE NO. (915) 683-3344

(This space for State Use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE ORIGINAL SIGNED BY DATE NOV 06 2001
GARY W. WINK
NATURAL SCIENCE MANAGER - 2



FINA OIL AND CHEMICAL COMPANY

SHEET NO.

FILE

DATE

BY

Monanto State #2

Lea Co N. Mex

660 FEL : 660 FSL sec 16 T-25S R-32E

2-10-92

SGK

GL 3424

KB 3433

SPUD 10-28-60

COMP 11-6-60

#1 4623-73

Cased #2 4676-4713

#3 4713-4768

10 3/4 32.75 # @ 351'

Cmt w/190 SX

13 3/4" Hole

TOC @ Surf By core

PERF 4662-71 w/4 JSPF

11-13-60

ACDED 500 gal MCA

FRAC ? 500 gal MCA 1000 gal LC w/500 =

10-20 : 500 # 20-40 SD

IPF 53.9 BO in 19 HRS

Recompletion

12-16-62-69 Perforated w/1 JSPF

4630-60

ACDED 750 gal 15% NE w/
65 Bagel SolidsFRAC 20000 gal gelled (Lact 5:1
w/30000# 10-20 SD

FLWD RT FO 56 BW on 10/4 choke

@ 360# FTP

11-27-72

Put on pump

5 1/2 14:17 # @ 4767

Cmt w/150 SX

7 1/8" Hole

TOC @ 3624'

TD 4768'

LOGSSONIC 0-4763 11-6-60 Schlumberger
LATER LOG 4560-4761 11-6-60 "