

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08199
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-0789-1
7. Lease Name or Unit Agreement Name MONSANTO STATE
8. Well No. 4
9. Pool name or Wildcat PADUCA; DELAWARE
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,425 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator V-F PETROLEUM INC.
3. Address of Operator P.O. BOX 1889, MIDLAND, TEXAS 79702
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1,980</u> Feet From The <u>WEST</u> Line Section <u>16</u> Township <u>25-S</u> Range <u>32-E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,425 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(SEE REVERSE)

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Wayne Luna TITLE PRODUCTION SUPERINTENDENT DATE 11/03/01

TYPE OR PRINT NAME M. WAYNE LUNA TELEPHONE NO. (915) 683-3344

(This space for State Use)

APPROVED BY GARY W. WINK TITLE ORIGINAL SIGNED BY DATE NOV 06 2001

CONDITIONS OF APPROVAL, IF ANY:

NATURAL SCIENCE MANAGER - 2

1. MIRU PLUGGING RIG. PULL ALL PRODUCTION EQUIPMENT.
2. RUN & SET CIBP @ 4,490'. DUMP BAIL 35' OF CEMENT 4,465' - 4,490'.
3. PULL STRETCH ON 5 1/2" CSG. SHOOT CASING AT FREE POINT EST 3,900'.
4. PULL CASING.
5. RUN TUBING TO 50' INSIDE CASING STUB.
6. BREAK CIRCULATION WITH MUD LADEN SALT WATER.
7. SPOT 100' CEMENT PLUG.
8. PULL BOTTOM OF TUBING TO 3,000'. SHUT DOWN WOC FOR 4 HR. +.
9. RUN TUBING & TAG PLUG @ 50' ABOVE CASING STUB.
10. PULL BOTTOM OF TUBING TO 2,000'. SPOT 100' CEMENT PLUG 1,900' - 2,000'.
11. PULL BOTTOM OF TUBING TO 310'.
12. SPOT 100 SX CEMENT 210' - 310'.
13. PULL TUBING OUT OF HOLE. WOC 4 HR. +.
14. RUN TUBING & TAG CEMENT @ 210'.
15. PULL TUBING & SET 30' CEMENT PLUG 0-30'.
16. CUT OFF 5 1/2" X 8 5/8" WELLHEAD.
17. INSTALL DRY HOLE MARKER.

Monsanto State #4

